

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	For <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR		7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY		8. Farm or Lease Name SECTION 25
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001		9. Well No. 431
4. Location of Well UNIT LETTER I, 330 FEET FROM THE EAST LINE AND 2310 FEET FROM THE SOUTH LINE, SECTION 25 TOWNSHIP 18-S RANGE 37-E NMPM.		10. Field and Pool, or Whicat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3649' GR		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER PLUG BACK WITH HYDROMITE TO IMPROVE INJECTION PROFILE <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out to PBTD (4060').
- Place a 15' hydromite plug (22 gals) from 4060' to 4045'.
- Wait for hydromite to gel. Tag new PBTD (+ 4050').
- Install injection equipment and return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Sexton A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE DECEMBER 7, 1983

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE DEC 13 1983

CONDITIONS OF APPROVAL, IF ANY: