	State of New Mex		Form C-103
Office District I	Energy, Minerals and Natura	l Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240			30-025-05511
District II	OIL CONSERVATION I	DIVISION	
1301 W. Grand Ave., Artesia, NM 88210	sia, NM 88210 1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE FEE X
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875		STATE FEE X  6. State Oil & Gas Lease No.
District IV	Santa Fe, Ivivi 675	03	
1220 S. St. Francis Dr., Santa Fe, NM			10646
87505 SUNDRY NOTIO	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:
TO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUC	BACK TO A	
	ATION FOR PERMIT* (FORM C-101) FOR	SUCH	McMillan
PROPOSALS.)  1. Type of Well:			
	Other		
2. Name of Operator			8. Well No.
SOUTHWEST ROYAL	TIES, INC.		1
3. Address of Operator			9. Pool name or Wildcat
P.O. BOX 11390	MIDLAND, TEXAS 7	9707	EUMONT/YATES SR-9n
4. Well Location			
	CCO fact from the SOUTH	l line and	1980 feet from the WEST line
Unit Letter N :	660 feet from the SOUTE		1000 1000 1100
04:	Township 185 Ran	ge 37E	NMPM LEA County
Section 29	10. Elevation (Show whether DR,	RKB. RT. GR. etc	
	3730 ' DR		
11 Check A	Appropriate Box to Indicate Na	ture of Notice,	Report or Other Data
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
PERFORM REMEDIAL WORK	1 200 7 11 2 7 2 7 11 2 9 11 2		_
TEMPORARILY ABANDON 🗵	CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND
LEMILOUVILLI VIDVIADOIA 63			ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND 🗆
	COMPLETION	CEMENT JOB	
	п	OTHER:	
OTHER:			1 1
1.44	dtions (Clearly state all pertin	nent details, and gi letions: Attach w	ve pertinent dates, including estimated date of ellbore diagram of proposed completion or
<ol> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> </ol>	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Comp	etions: Attach w	enbore diagram of proposed completion of
12. Describe proposed or complete starting any proposed work). SI recompilation.	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Comp	ON EOUIPME	NT.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> </ul>	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Comp	ON EOUIPME	enbore diagram of proposed completion of
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> <li>3) LOAD CASIN</li> <li>4) TEMPORARIL</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> <li>3) LOAD CASIN</li> <li>4) TEMPORARIL</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Comp  F HOLE WITH PRODUCTI LE WITH CIBP AND SET	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> <li>3) LOAD CASIN</li> <li>4) TEMPORARIL</li> </ul>	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
<ul> <li>Describe proposed or complete starting any proposed work). SI recompilation.</li> <li>1) TRIP OUT O</li> <li>2) TRIP IN HO</li> <li>OF CEMENT.</li> <li>3) LOAD CASIN</li> <li>4) TEMPORARIL</li> </ul>	d operations. (Clearly state all pertine RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.
12. Describe proposed or complete starting any proposed work). Si recompilation.  1) TRIP OUT O 2) TRIP IN HO OF CEMENT. 3) LOAD CASIN 4) TEMPORARIL	d operations. (Clearly state all pertine EERULE 1103. For Multiple Composition of the Product of the Market of the Service of	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.  ge and belief.  ERVISOR DATE 8/29/02
12. Describe proposed or complete starting any proposed work). SI recompilation.  1) TRIP OUT O 2) TRIP IN HO OF CEMENT. 3) LOAD CASIN 4) TEMPORARIL	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.  ge and belief.  ERVISOR DATE 8/29/02
12. Describe proposed or complete starting any proposed work). Si recompilation.  1) TRIP OUT O 2) TRIP IN HO OF CEMENT. 3) LOAD CASIN 4) TEMPORARIL	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT  est of my knowled AREA SUP	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.  ge and belief.  ERVISOR DATE 8/29/02
12. Describe proposed or complete starting any proposed work). SI recompilation.  1) TRIP OUT O 2) TRIP IN HO OF CEMENT. 3) LOAD CASIN 4) TEMPORARIL	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Composition of the Product of the With CIBP and Set of the With CIBP and Set of the With TREATED WATER OF ABANDON WELL PENDINE TITLE.  The Composition of the Bound of the	ON EQUIPME AT APPROX AND TEST NG EVALUAT  est of my knowled AREA SUP	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.  ge and belief.  ERVISOR DATE 8/29/02  Telephone No.915/686-9
12. Describe proposed or complete starting any proposed work). SI recompilation.  1) TRIP OUT O 2) TRIP IN HO OF CEMENT. 3) LOAD CASIN 4) TEMPORARIL	d operations. (Clearly state all pertine EE RULE 1103. For Multiple Composite F HOLE WITH PRODUCTI LE WITH CIBP AND SET G WITH TREATED WATER Y ABANDON WELL PENDI	ON EQUIPME AT APPROX AND TEST NG EVALUAT  est of my knowled AREA SUP	NT 3600'. CAP WITH 35' TO 500 PSIG. ION OF SHALLOW ZONES.  ge and belief.  ERVISOR DATE 8/29/02  Telephone No. 915/686-9