Submit 3 Copies to Appropriate District Office

Þ

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II DISTRICT II					N	WELL API NO. 30-025-07339			
P.O. Drawer DD, Artesia, NM 88210						Indicate Typ	pe of Leas	e –	
	10				·	State Oil & (Gas Leas	STATE	FEE 🔀
1000 Rio Brazos Rd., Aztec, NM 874	10								
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						-Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit			
Type of Well: OIL GAS WELL WELL WELL	. []	OTHER OL	servati	on Well					
Name of Operator Altura Energy, LTD						-Well No. 131		<u> </u>	
Address of Operator		. <u> </u>				Pool name		t	
1017 Stanolind Rd. Hobbs, Well Location	New Mexico	<u> </u>				Hobbs ((G/SA)		·
Unit Letter 2	2310 Feet F	rom TheSouth	า	_ Line and3	330	Feet Fr	om The	West	Line
Section	18 т	ownship 185	а Т	Range 3	8E	NMPM		Lea	County
		⇔Elevation (Show whe 3676 DF	ther DF, I	RKB, RT, GR, etc.)					
¹¹ Che	ck Approp	oriate Box to Indica	ate Na	ture of Notice	Rep	ort, or O	ther D	ata	
NOTICE C				1	-			PORT OF	
ERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK				ALTERING CAS	SING
EMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILL	LING OF	NS.		PLUG AND ANE	ANDONMENT
ULL OR ALTER CASING				CASING TEST AND		NT JOB			
)THER:									
				OTHER:					
Describe Proposed or Completed O work) SEE RULE 1103.		ny state all pertinent details,	and give		ding est	imated date o	f starting a	any proposed	
Describe Proposed or Completed O	tent to plug nt below pkr hole 275'; Tag plu m 30' to surfa	@ 1000'; Disp. cmt to ng @ 153' ace			ding est	imated date o	f starting a	any proposed	
Describe Proposed or Completed O work) SEE RULE 1103. 2-24-00 Notify NMOCD of ini 2-25-00 Squeeze 400 sxs cn 2-28-00 Tag plug @ 1476' 2-28-00 Mix mud& circulate h 2-28-00 Spot 45 sxs cmt @ 2 2-28-00 Spot 15 sxs cmt fror	tent to plug nt below pkr hole 275'; Tag plu m 30' to surfa d install dry h above is true and	@ 1000'; Disp. cmt to ng @ 153' ace ole marker	1500' knowled	pertinent dates, includ ge and belief.				any proposed	1-00
Describe Proposed or Completed O work) SEE RULE 1103. 2-24-00 Notify NMOCD of int 2-25-00 Squeeze 400 sxs cn 2-28-00 Tag plug @ 1476' 2-28-00 Mix mud& circulate h 2-28-00 Spot 45 sxs cmt @ 2 2-28-00 Spot 15 sxs cmt fror 2-29-00 Cut off wellhead and SIGNATURE	tent to plug nt below pkr hole 275'; Tag plu m 30' to surfa d install dry h	@ 1000'; Disp. cmt to ng @ 153' ace ole marker d complete to the best of my	1500' knowled	pertinent dates, includ ge and belief.					
Describe Proposed or Completed O work) SEE RULE 1103. 2-24-00 Notify NMOCD of int 2-25-00 Squeeze 400 sxs cm 2-28-00 Tag plug @ 1476' 2-28-00 Mix mud& circulate h 2-28-00 Spot 45 sxs cmt @ 2 2-28-00 Spot 15 sxs cmt fror 2-29-00 Cut off wellhead and SIGNATURE	tent to plug nt below pkr hole 275'; Tag plu m 30' to surfa d install dry h	@ 1000'; Disp. cmt to ng @ 153' ace ole marker d complete to the best of my	1500' knowled	pertinent dates, includ ge and belief.				DATE 03-0	
Describe Proposed or Completed O work) SEE RULE 1103. 2-24-00 Notify NMOCD of int 2-25-00 Squeeze 400 sxs cn 2-28-00 Tag plug @ 1476' 2-28-00 Mix mud& circulate h 2-28-00 Spot 45 sxs cmt @ 2 2-28-00 Spot 15 sxs cmt fror 2-29-00 Cut off wellhead and SIGNATURE	tent to plug nt below pkr hole 275'; Tag plu m 30' to surfa d install dry h above is true and	@ 1000'; Disp. cmt to ng @ 153' ace ole marker d complete to the best of my	1500' knowled	ge and belief.	Ρ&Α:	Supervisor		DATE 03-0	