

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- INJECTOR

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

Name of Operator
SHELL WESTERN E&P INC.

8. Field or Lease Name
SECTION 19

Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

9. Well No.
112

Location of Well
UNIT LETTER D 990 FEET FROM THE NORTH LINE AND 990 FEET FROM
THE WEST LINE, SECTION 19 TOWNSHIP 18-S RANGE 38-E WPM.

10. Field and Pool, or Whichever
HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)
3671' DF

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER PERF, ACIDIZE & SQZ ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1. Pull inj equip.
2. CO to 4254'.
3. Run csg inspection log from 4000' to 4254'.
4. Perf San Andres 4162' - 4222' (2 JSPF, 78 holes).
5. Acidize perfs 4162' - 4222' w/4000 gals 15% HCl.
6. Acid treat San Andres OH 4254' - 4276' w/500 gals xylene + 3000 gals 15% HCl.
7. Run base/GR log from 4000' - 4254'.
8. Set CIBP @ 4160' & cap w/10' cmt.
9. Set CIGR @ 4090'.
10. Sqz San Andres perfs 4127' - 4149' w/100 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco suds + 0.75% HC-2. WOC 24 hrs.
11. DO CIGR & cmt to 4155'. Pres tst sqz to 700# for 15 min.
12. DO CIBP @ 4160'. CO to csg shoe @ 4254'.
13. Run base/GR log from 4000' - 4254'.
14. Install inj equip & return well to inj.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

 A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE FEBRUARY 17, 1987
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 20 1987

RECEIVED
FEB 19 1987
OCD
#OBBS OFFICE