

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO	30-025-07376
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	North Hobbs (GB/SA) Sec 20
8. Well No.	432
9. Pool name or Wildcat	Hobbs (GB/SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Altura Energy, LTD.	3. Address of Operator P.O. Box 4294 Houston, Texas 79210-4294
4. Well Location Unit Letter <u>I</u> : <u>1850</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>20</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>Lea NM</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3655' GR</u>	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PULLING UNIT, NUBOP.
- 2) RIH W/2-3/8" WORKSTRING, TAG, RET @ 3986'.
- 3) CIRC HOLE W/9.5# MLF.
- 4) SPOT 30 SXS CMT ON TOP OF RET FROM 3986'-3807'.
- 5) PERF 7" CSG @ 2640', SET 7" RET @ 2540', SQZ W/50 SXS, CAP RET W/30 SXS.
- 6) PERF 7" CSG @ 1665', SET 7" RET @ 1565', SQZ W/50 SXS, CAP RET W/30 SXS.
- 7) PERF 7" CSG @ 297', SQZ W/60 SXS, DISPLACE TOC TO 197', WOC & TAG.
- 8) SPOT 10 SXS CMT FROM 30' TO SURFACE.
- 9) INSTALL DRY HOLE MARKER, RDMO.

NOTIFY NM OCD 24 HRS PRIOR TO RIGGING UP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE SENIOR P&A SUPERVISOR DATE 12/11/97
TYPE OR PRINT NAME ROGER MASSEY TELEPHONE NO. 915-530-0907

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE DEC 12 1997
CONDITIONS OF APPROVAL, IF ANY: