November 1983) Formerly 9-331)		THE INTERI		re	es August 3	1, 1905
()()()()()()()()()()()()()()()()()()()		AND MANAGEMENT		LC-0322		ND SERIAL NO.
				_ /		OR TRIBE NAME
(Do not use this		AND REPORTS C 11 or to deepen or plug bi DR PERMIT—" for such pr	IN WELLS			
OIL CAS WELL WELL	OTESE			7. UNIT AGE	BEMENT NAM	E
NAME OF OPERATOR				8. FARM OR	LEASE NAME	
Exxon Corporation				Bowers	Bowers A Federal	
				9. WELL NO		
P. U. BOX 16 LOCATION OF WELL (E	00, Midland, TX	79702			1	
LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface				4	10. FIELD AND POOL, OE WILDCAT Hobbs Blinebry	
					5	
1980' FSL an	d 660' FEL of Se	с.		BURVI	R., M., OR BLI	L. AND
A. PERNIT NO					, 18S, 3	
I. FRANT NO.	15. ELE	VATIONS (Show whether DF,	•	12. COUNTY	OR PARISH	13. STATE
	<u> </u>	3657' DF		Lea		NM
3 .	Check Appropriat	e Box To Indicate No	ature of Notice, Report, c	or Other Data		
1	OTICE OF INTENTION TO:	1	508	SEQUENT REPORT () .	
TEST WATER SHUT-O	T PULL OR A	LTER CASING	WATER SHUT-OFF		EPAIRING WE	
FRACTURE TREAT	MULTIPLE	COMPLETE	FRACTURE TREATMENT		LTERING CAR	
SHOOT OR ACIDIZE	ABANDON*	x	SHOOTING OR ACIDIZING		BANDONMENT	• 1
REPAIR WELL	CHANGE PI	.ANE	(Other)			
(Other) DESCRIBE PROPOSED OR proposed work. If nent to this work.)	COMPLETED OPERATIONS (well is directionally drill		(Norz: Report res Completion or Rec details, and give pertinent da ons and measured and true ve	ompietion Report a	ind Log form.	.}
(Other) DESCRIBE (TROPOSED OR proposed work. If nent to this work.) We propose to 1. Instal 2. Set pl San Ar 7" csg 3. Set pl base c 4. Run fr w/ 100 5. Perfor establ salt. 6. If inj 7. Perfor 8. Establ 7" x 9	completed operations (well is directionally drill o'plug and aband dug 4100'-3550' dres and Queen. g. shoe. ug 2800'-2550' f the salt. eepoint and cut ' plug - 50' be ate 7" csg. at ished set 100' p ection is establ ate at 280' w/ 4 ish injection do 5/8" annulus.	Clearly state all pertinent ed. give subsurface location on the above well s to 500#. w/ 40 sx to cove and to cover old w/ 20 sx to cove 4 1/2" csg. (TO low and 50' above 1350' w/ 4 shots olug 1400'-1300' lished - squeeze + shots. own 7" csg. Circo Set surface plus	(Nors: Report res Completion or Rece details, and give pertinent da ins and measured and true ve 1 as follows: r top of Grayburg, Queen perforations r 9 5/8" csg. shoe C 2200'). Cover st e - w/ 15 sx. If injection is w/ 20 sx to cover w/ 100 sx down 7" culate up 9 5/8 x 1 z w/ 100 sx.	and and top of the csg.	ind Log form. Imated date (all markers a	.)
(Other) DESCRIBE (TROPOSED OR proposed work. If nent to this work.) We propose to 1. Instal 2. Set pl San Ar 7" csg 3. Set pl base or 4. Run fr w/ 100 5. Perfor establ salt. 6. If inj 7. Perfor 8. Establ 7" x 9 9. Instal	completed operations (well is directionally drill o'plug and aband 1 and test BOP' ug 4100'-3550' dres and Queen. ; shoe. ug 2800'-2550' f the salt. eepoint and cut ' plug - 50' be ate 7" csg. at ished set 100' p ection is establ ate at 280' w/ 2 ish injection do 5/8" annulus. 1 dry hole market he foregoing is true and ' Mupue rue	Clearly state all pertioent ed. give subsurface location on the above well s to 500#. w/ 40 sx to cove and to cover old w/ 20 sx to cove 4 1/2" csg. (TO low and 50' above 1350' w/ 4 shots olug 1400'-1300' lished - squeeze + shots. own 7" csg. Circo Set surface plug er, clean and lev	(Nor: Report res Completion or Rece details, and give pertinent da ins and measured and true ver 1 as follows: r top of Grayburg, Queen perforations r 9 5/8" csg. shoe C 2200'). Cover st e - w/ 15 sx. If injection is w/ 20 sx to cover w/ 100 sx down 7" culate up 9 5/8 x 1 g w/ 100 sx. yel location.	and and and top of the csg. 2 1/2" annu DATE.	ind Log form. Imated date (all markers a	-86

*See Instructions on Reverse Side