

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1-04-1
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT
2. NAME OF OPERATOR SHELL WESTERN E&P INC.	8. FARM OR LEASE NAME SECTION 30
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. WELL NO. 331
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface UNIT LTR J, 2335' FSL & 2310' FEL	10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)
14. XXXXXXXX API NO. 30-025-07472	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 30, T18S-R38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3654' DF	12. COUNTY OR PARISH LEA
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☒

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Pull production equipment.
2. Release RBP @ 4054' & POH.
3. PB to 4170' w/sand.
4. Tag top of sand. PB w/cmt to #4161'.
5. Set CIGR @ 3975'. Sqz Grayburg/San Andres perms 4010' - 4160' w/100 sx CIs "C" cmt + 2% CaCl₂ + 1.5% Howco suds + .75% HC-2. WCC 24 hrs.
6. DO CIGR and cmt. Pres tst sqz while drilling. Tag CIBP @ 4220'.
7. CO sand to PBD (4220').
8. Install production equipment and return well to production.

18. I hereby certify that the foregoing is true and correct:

SIGNED E. C. Fore A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE NOVEMBER 20, 1986

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 12-2-86

*See Instructions on Reverse Side