

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032233 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BOWERS "A" FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

HOBBS (G-SA)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC. 30, 18-S, 38-E

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

EXXON CORPORATION

3. ADDRESS OF OPERATOR

P.O. Box 1600, MIDLAND, TX. 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface2335' FSL & 2310' FEL  
SEC 30, 18-S, 38-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

DF 3654

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) \* SEE BELOW

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*\* INCREASE LIFT CAPACITY AND GO BACK TO PREVIOUS  
COMPLETION INTERVAL.PULL RODS AND PUMP, RELEASE PACKER AND PULL OUT  
OF HOLE.

RUN RETRIEVING HEAD ON TUBING, LATCH ONTO BP &amp; POH.

RUN A PERMANENT BRIDGE PLUG ON TUBING AND SET AT  
4100'.

CHANGE OUT RODS, TUBING, AND PUMP.

PUT WELL ON PRODUCTION

18. I hereby certify that the foregoing is true and correct

SIGNED

D. L. Clemmer

TITLE

UNIT HEAD

DATE

7-29-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Jim L...