STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MOITURIATEID		Γ
SANTA FE		
FILE		
U.S.G.S.		_
LAND OFFICE		
DEFEATOR	- I	

OIL CONSERVATION DIVISION

1 0	P. O. BOX 2088	Form C-103
<u> </u>	331 1130 1101	Revised 10-1-78
FILE	SANTA FE, NEW MEXICO 87501	5a. Indicate Type of Lease
U.S.		
	OOFFICE	State XX Fee
	RATOR	5. State Oil & Gas Lease No.
	CONTRACTOR AND DEPORTS ON WELLS	
10	SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUGGED BACK TO A DIFFERENT RESERVOIR.	
	USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1.		
OIL WELL	WELL OTHER INJECTOR	N. HOBBS (G/SA) UNIT
2. Name of	Operator	8. Farm of Lease Name
CHEI	L OIL COMPANY	SECTION 33
	of Operator	9. Well No.
į.		141
	. BOX 991, HOUSTON, TX 77001	10. Field and Pool, or Wildcat
4. Locatio		HODDS (C/SA)
UNIT	ETTER M . 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM	THOBBS (G/SA)
1		
	WEST LINE, SECTION 33 TOWNSHIP 18-S RANGE 38-E NMPM.	
THE -	51051 555 755	
TITTE	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3635' GR	LEA ())))))
77777		
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
BY B F OB M	REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	CONVENCE DRIVING OPES	PLUG AND ABANDONMENT
	ILV ASANDON	
PULI. OR A	CHANGE PLANS CASING TEST AND TEMENT TO THER	
	OPEN ADDITIONAL PAY AND ACIDIZE XX	
OTHER	OPEN ADDITIONAL PAT AND ACIDIZE NA	
	the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work)	SEE RULE 1103.	
·		
	Set RBP @4225'. Pressure test to 500 psi. Spot 15' sand on top.	
1		
1.	Set RBP @4225'. Pressure test to \$\frac{500}{900} psi. Spot 15' sand on top.	
1.	Set RBP @4225'. Pressure test to \$\frac{500}{500} psi. Spot 15' sand on top.	
2.		
2.	Set RBP @4225'. Pressure test to \$\frac{500}{500} \text{ psi. Spot 15' sand on top.} Run CBL/VDL/CCL/GR from TD (4210') to surface.	
2.	Run CBL/VDL/CCL/GR from TD (4210') to surface.	ross zone to be perf'd
2.		ross zone to be perf'd.
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac	
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho	les), 4080' (2 holes),
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4	les), 4080' (2 holes), 143' (2 holes), 4146'-
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes)	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes)	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236'	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30
2. 3. 4.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) -
2. 3.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
2. 3. 4.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 3. 4. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 3. 4. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 3. 4. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 2. 3. 4. 6. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi Re-run production equipment and return well to production.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 2. 3. 4. 6. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 2. 3. 4. 6. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi Re-run production equipment and return well to production.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem-
 3. 4. 6. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 holes), 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi Re-run production equipment and return well to production.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem- pe.
 2. 3. 4. 6. 	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 ho 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi Re-run production equipment and return well to production.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem- pe.
2.3.4.5.6.	Run CBL/VDL/CCL/GR from TD (4210') to surface. Reverse off sand. Retrieve bridge plug. Spot 200 gals 15% HCl ac Perf 5" csg top down 4062' (2 holes), 4066' (2 holes), 4069' (2 holes), 4106'-4113' (16 holes), 4117' (2 holes), 4130'-4137' (16 holes), 4153' (16 holes), 4162'-4168' (10 holes), 4178' - 4188' (22 holes) holes), 4216' - 4222' (14 holes), 4226' - 4230' (10 holes), 4236' Total 174 holes. CO to 4254'. Acidize perfs w/5400 gals 15 % HCl-NEA acid using a bly w/24' spacing and collar locator on top. Test SPA in blank pi Re-run production equipment and return well to production.	les), 4080' (2 holes), 143' (2 holes), 4146'- , 4194' - 4208' (30 - 4249' (28 holes) - straddle packer assem- pe.