

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator SHELL OIL COMPANY 3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001 4. Location of Well UNIT LETTER <u>J</u> <u>1920</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1780</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMFM. 15. Elevation (Show whether DF, RT, GR, etc.) 3644' GR	7. Unit Agreement Name N. HOBBS (G/SA) UNIT 8. Farm or Lease Name SECTION 33 9. Well No. 331 10. Field and Pool, or Wildcat HOBBS (G/SA) 12. County LEA
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>WATER SHUT-OFF</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Plug back w/sand to 4072'±.
2. Set 4-1/2" FBP @ 3700'±.
3. Squeeze cement perforations 4047' to 4054' with 50 sx Class "C" cement plug .3% Halad-4. WOC 24 hrs.
4. Clean out to 4072'±. Pressure test squeeze to 500 psi. If squeeze does not hold, re-cement with 50 sx Class "C" cement. WOC 24 hrs.
5. Clean out to 4232'±, install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JUNE 21, 1983
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR
APPROVED BY _____ TITLE _____ DATE JUN 28 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 27 1983

C.C.D.
HOBBS OFFICE