

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-

1. Indicate type of lease	State ☐	Fee ☐
2. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM TO RESPOND TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Field or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 7
4. Location of well UNIT LETTER <u>N</u> <u>1080</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>34</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NEPM.	10. Field and Pool, or Wildcat Hobbs GSA
11. Elevation (Show whether DF, RT, GR, etc.) 3613' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
FULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Briefly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to acid fracture to increase oil production. Pull rods and pump. Tag bottom at 4218' with tubing. Circulate out any fill & pull tubing. Run tubing and packer. Set packer at approx 4000'. Run base temperature survey 4000'-4218'. Acid fracture the San Andres Formation as follows: At 9-10 BPM pump 1000 gals of 2% HCL acid. Pump 8000 gals of High Vis. gelled frac pad in 4 equal stages followed by 2000 gals of 20% HCL acid in each stage. Pump 500 gals of gelled 10# brine carrying 500 lbs of graded rock in stages 1, 2, and 3. Flush and overflush with 40 bbls of fresh water with additives. Run temperature survey 4000'-4218'. Pull packer and tubing. Return well to production.

0+4-NMOCD, H 1-Hou 1-Susp 1-CLF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Ferman TITLE Assist. Admin. Analyst DATE 11-25-81
Orig. Signed By
APPROVED BY Jerry Sexton TITLE DATE
CONDITIONS OF AMENDMENT: Dist 1, Supp.