

CONSERVATION DIVISION
P. O. BOX 2068
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

2. DEPARTMENT OF MINES AND METALS	
3. DIVISION	
4. COUNTY	
5. FIELD	
6. U.S.G.S.	
7. LAND OFFICE	
8. OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR MATERIALS TO BE FILED OR TO OBTAIN OR FILED IN A DIFFERENT DISTRICT.
SEE APPROPRIATE INSTRUCTIONS FOR REPORTING FORM C-101 FOR SUCH MATERIALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Petro Lewis Corp.

ADDRESS OF OPERATOR

200 Ave L, Eunice New Mexico

LOCATION OF WELL

UNIT LETTER A 660 FEET FROM THE 2 LINE AND 660 FEET FROM

WELL E LINE, SECTION 36 TOWNSHIP 18 RANGE 36 NEQU.

11. Direction (Show Leaser DR, RT, GR, etc.)

13. Indicate Type of Lease

State ☒ Fee ☐

14. State Oil & Gas Lease No.

15. Unit Agreement Name

16. Form of Lease Name

State A

17. Well No.

X-2

18. Field and Foot, or Locality

Eumont

19. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

1. PLUG AND ABANDON WORK ☐

2. PLUG AND ABANDON WORK ☐

3. PLUG AND ABANDON WORK ☐

4. PLUG AND ABANDON WORK ☒

5. PLUG AND ABANDON WORK ☐

6. PLUG AND ABANDON WORK ☐

7. PLUG AND ABANDON WORK ☐

8. PLUG AND ABANDON WORK ☐

9. PLUG AND ABANDON WORK ☐

10. PLUG AND ABANDON WORK ☐

11. PLUG AND ABANDON WORK ☐

12. PLUG AND ABANDON WORK ☐

13. PLUG AND ABANDON WORK ☐

14. PLUG AND ABANDON WORK ☐

15. PLUG AND ABANDON WORK ☒

16. PLUG AND ABANDON WORK ☐

17. PLUG AND ABANDON WORK ☐

18. PLUG AND ABANDON WORK ☐

19. Give a brief description of Completed Operations (Clearly state all pertinent details, and give pertinent facts, including estimated date of starting any proposed work.) SEE RULE 1103.

- 12-14-81 Road to location, rig up 12-15-81. Pull and lay down rods, Pull tubing, had 3540' in well.
- 12-16-81 Pick up and run tubing out of derrick to 4920'. Spot 80 sacks of cement @ 4920, pull 30 joints, shut down.
- 12-17-81 Went down & tag plug @ 4480', displace hole with 10 lbs. of salt water gel. Came up to 3201', spot 25 sacks cement. Came out of hole.
- 12-18-81 Went in hole with wire line. Perforate 5 holes @ 1560'. Went in hole with tubing, try to pump in it. Could not pump into it. Pump 25 sacks of cement @ 1560' to 1423'. Came out of hole (12-19-81).
- 12-20-81 Cut off well head, dump 10 sacks cement & set dry hole marker. Rig down, cut off anchors

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

By Rudolph B. B. B.

TITLE Inspector

DATE 2-4-82

APPROVED BY W. A. Gattormini

TITLE

OIL & GAS INSPECTOR

DATE

1111 2 1982

ADDITIONS OF APPROVAL, IF ANY: