

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3-10000
1-File

5a. Indicate Type of Lease
State ☐ Fee ☐

5. State Oil & Gas Lease No.
B-7653

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GIFTY OIL COMPANY	8. Farm or Lease Name STATE AN
3. Address of Operator P.O. Box 249, Hobbs, New Mexico 88240	9. Well No. 8
4. Location of Well UNIT LETTER P , 330 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Vacuum Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3968 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to Plug and Abandon this well as follows:

**Fill both the 2-7/8" and 4-1/2" Casing with sand.
In 4-1/2" Casing lay 25 sack Class C Cement Plug from T.D. @ 11,785' to 11,405'.
Cut 4-1/2" & 2-7/8" Casing where it is free (Top of Cnt. @ 5150')
Lay 25 Sack Plug on Top of the 4-1/2" & 2-7/8" Stubs.
Lay 50 sack plug in and out of 9-5/8" Casing from 3500' to 3340'.
Place 10 Sack Plug @ Surface and erect marker.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By

SIGNED O. L. WADE TITLE Area Superintendent DATE November 11, 1969

APPROVED BY [Signature] TITLE DATE 1969

CONDITIONS OF APPROVAL, IF ANY: