BEFORD OF DRILL-STEM AND SPECIAL TEST.

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto

TOOLS USED

Rotary t	ools we	re used from.	Surface feet	to		·····	feet to /feet				
Cable tools were used from						,				***************************************	fcet.
			20 62		RODUCTION						•
				, 19							
OIL WI			on during the first 24 l								
		was oil;	0 % was	emulsion;	0	% wate	r; and	0	.% was	sedimen	t. A.P.I.
			37.2				•		.,,		. 16.1.4.
GAS WI		·									
OAS III			on during the first 24 h			.м.с.г. р	lus	***************************************	••••••	b	arrels of
			carbon. Shut in Pressur	,							
PLE	EASE I	NDICATE I	BELOW FORMATIO	N TOPS (IN	CONFORMAN	CE WIT	н сеосі	RAPHICAL SE	CTION	OF STA	ATE):
			Southeastern New					Northwest	ern New	Mexico	•
	•							Ojo Alamo			
					***************************************			Kirtland-Fruit			
			Т		••••••			Farmington			
T. 7 Rivers				1, 110					Pictured Cliffs		
T. Queen 4134									Point Lookout		
T. Grayburg									Mancos		
T. San Andres									Dakota		
T. Glorieta								Morrison	•••••	•••••	•••••
T. Drinkard									•••••••		
T. Abo									•••••••		
			_	• •							
				•	TION RECO		······· A.		***********	•••••••••••	
	T	Thickness					Thickness	.1		· · · · · · · · · · · · · · · · · · ·	
From	То	in Feet	Forma	tion 	From	To	in Feet		Formatio	n	
			-	•							
	ľ										
•											
								,			
4											
							,				
									_		
		1		· · · · · · · · · · · · · · · · · · ·					F		
			ATTACH SEPAR.	ATE SHEET	IF ADDITIO	NAL SPA	CE IS NI	EEDED			

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far

Position of Title Agent

Company or Operator Marlo Drilling Co. Address Box 352, Midland, Texas

as can be determined from available records.