

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>36-025-70240</u>
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1258
7. Lease Name or Unit Agreement Name New Mexico "AE" State
8. Well No. 7
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>18S</u> Range <u>34E</u> NMMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3988' DF</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). Notify NMOCDD before plugging.
- 2). MIRU pulling unit. Install BOP.
- 3). Fish pump located at approximately 6000'.
- 4). TIH w/workstring and 2 7/8" bit. Clean out to 8800'. TOH w/bit and ws. RDP.
- 5). By wireline, set CIBP at 8750'. Cap w/35' of class "H" cmt (1sx).
- 7). Set CIBP at 5300'. Cap w/35' of class "H" cmt.
- 8). Set CIBP at 3275'. Cap w/35' of class "H" cmt.
- 9). Set CIBP at 2780'. Cap w/35' of class "H" cmt.
- 10). Set CIBP at 1925'. Cap w/35' of class "H" cmt.
- 11). Set CIBP at 330'. Cap w/35' of class "H" cmt.
- 12). Spot surface plug of 10 sxs (303').
- 13). Cut off wellhead. Install dry hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard DeSoto TITLE Engineering Technician DATE 07-24-91

TYPE OR PRINT NAME R. B. DeSoto TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: