

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
8-1258-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
TEXACO Inc.
3. Address of Operator
P.O. Box 723, Hobbs, New Mexico 88241
4. Location of Well
Unit Letter E 2310 FEET FROM THE North LINE AND 330 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 18S RANGE 34E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)
3810' (RT)

7. Unit Agreement Name
-
8. Farm or Lease Name
New Mexico "AE" State
9. Well No.
8
10. Field and Pool, or Wildcat
Vacuum Abo Reef
12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up.
2. Set CIP 8 3375' around 55 sx. cement on plug.
3. Spot 20 sx cement plug from 3320'-2600'.
4. Cut 2-7/8" OD casing 1015' and pulled same.
5. Spot 70 sx cement plug from 1710-1510'.
6. Spot 50 sx cement plug from 420'-270'.
7. Pump 40 sx cement down 3-5/8". Plug to surface.
8. Install dry hole marker & clean up. Well shut in 4-25-77.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 4-23-77

APPROVED BY [Signature] TITLE OIL & GAS DIRECTOR DATE 5-1-77

CONDITIONS OF APPROVAL, IF ANY: