			Form 3-103
NO. OF COPIES RECEIVED			Supersedes Old C-102 and C-103
DISTRIBUTION	NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
SANTA FE	€	는 경험원호 	5a. Indicate Type of Lease
U.S.G.S.	3 - NMOCC - Hobbs	28 2 <u>24 85</u> 7	State X Fee
LAND OFFICE	l - File	1 25 m 31	5, State Oil & Gas Lease No.
OPERATOR			E-7571
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)			
	FOR PERMIT - " (FORM C-101) FOR SUCH	PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL	OTHER- Dry		
Name of Operator		9, Form or Lease Name	
Tidewater Oil Company		State "AS"	
3. Address of Operator		1	
Box 249, Hobbs, New Mexico		10. Field and Pool, or William	
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET			
UNIT LETTER E . 19	80 FEET FROM THE NOT TH	LINE AND FEET	FROM
	7 185	37 E	
THE West LINE, SECTION	7 TOWNSHIP 18S	RANGE	·
mmmm	15. Elevation (Show whether I	DF, RT, GR, etc.)	12. County
	3775 GR		Lea (\\\\\\\\
The Chack A	ppropriate Box To Indicate N	ature of Notice, Report of	or Other Data
NOTICE OF IN		SUBSEQ	UENT REPORT OF:
110 1100			7
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT 🍱
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JCB	٠
		OTHER	
OTHER			
·			
17. Describe Proposed or Completed Oper work) SEE RULE 1103.			
Set cast iron brid fill up.) Cut 2 978'. Laid 25 sa back to surface.	dge plug at ЩОО'. Dump	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid	
Set cast iron brid fill up.) Cut 2 978'. Laid 25 sa back to surface.	dge plug at 4400'. Dump -7/8" casing at 1103'. ck cement plug from 325 Installed marker.	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid	on top of plug. (15'
Set cast iron bridfill up.) Cut 2. 978. Laid 25 sa back to surface.	dge plug at 4400'. Dump -7/8" casing at 1103'. ck cement plug from 325 Installed marker.	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid	on top of plug. (15'
Set cast iron brid fill up.) Cut 2 978. Laid 25 sa back to surface. Location and pits	dge plug at 4400. Dump -7/8" casing at 1103. ck cement plug from 325 Installed marker.	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid cleaned up.	on top of plug. (15'
Set cast iron brid fill up.) Cut 2 978'. Laid 25 sa back to surface.	dge plug at 4400. Dump -7/8" casing at 1103. ck cement plug from 325 Installed marker.	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid cleaned up.	on top of plug. (15' plug from 1103 back to 10 sack cement plug from 14
Set cast iron brid fill up.) Cut 2 978. Laid 25 sa back to surface. Location and pits	dge plug at 4400. Dump -7/8" casing at 1103. ck cement plug from 325 Installed marker.	ped 1/2 sack cement Laid 25 sack cement back to 200'. Laid cleaned up.	on top of plug. (15'

CONDITIONS OF APPROVAL, IF