

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1080-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name New Mexico "M" State
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240	9. Well No. 5
4. Location of Well UNIT LETTER <u>D</u> <u>760</u> FEET FROM THE <u>West</u> LINE AND <u>560</u> FEET FROM THE <u>North</u> LINE, SECTION <u>1</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Whdcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 4010 (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <u>Perforate additional Glorieta pay</u> <u>Restore zone active status</u> <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Squeeze existing perforations at 6044-6046' with 50 sacks of cement.
2. Drill out CIBP at 6100'. Set new CIBP at 6500'.
3. Perforate Glorieta 2 SPI at 6100-04, 07, 14, 26, 29, 34, 38, 42, 60-66, 6169' (20 intervals, 40 shots total).
4. Acidize with 4200 gallons 15% NEFE HCL and 40 ball sealers.
5. Swab test and evaluate.
6. Install artificial lift equipment. Restore zone to active status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Howard H. Smith 393-4031
A. Gernandt TITLE Area Superintendent DATE 11/11/78

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY DATE 11/11/78 1987
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

12 2 1987

OCB
HONOLULU
110835 OFFICE