

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

B-3936-1

X Fee

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERFORATE OR TO TEST A DIFFERENT ZONE. USE APPLICATION FOR PERMIT FOR DRILLING, REPERFORATING OR TESTING PROPOSALS.

1. OIL GAS WELL OTHER _____

2. Name of Operator: **TEXACO INC.** N.M. 'AA' State **NCT-4**

3. Address of Operator: **P. O. Box 728 - Hobbs, New Mexico 88240** 2

4. Location of Well: UNIT LETTER **A** **660** FEET FROM THE **East** LINE AND **660** **Vacuum Abo Reef**

THE **North** LINE, SECTION **10** TOWNSHIP **18-S** RANGE **34-E**

5. Elevation (Show whether DF, RT, GF): **4027' (DF)** **Lea**

16. Check Appropriate Box To Indicate Nature of Non-Compliance or Other Action

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	RE-INSTALL CASE <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMPLETION <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CLEAN <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, including work) SEE RULE 1103.

1. Set CIBP in 2-7/8" @ 5200' and spot 35' (1 sx) on top of CIBP.
2. Load hole w/mud (25 sx gel per 100 bbls wtr).
3. Ran freepoint. Stuck at 774'.
4. Spot 100' (35 sx) cement 1700'-1600'. Plug #1.
5. Pulled 800' 2-7/8" OD csg.
6. Spot 140' (35 sx) cement 850'-710'. Plug #2.
7. Spot 20' (35 sx) cement plug @ surface.
8. Install dry hole marker and clean location.

Well Plugged & Abandoned 9-3-75

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED: *[Signature]* TITLE: **Assistant District Superintendent** 9-4-75

APPROVED BY: *[Signature]* TITLE: _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 16 1975