

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20555
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1189-1
7. Lease Name or Unit Agreement Name N.M. "AC" STATE NCT-1
8. Well No. #8
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	
3. Address of Operator P. O. Box 730, Hobbs, New Mexico 88240	
4. Well Location Unit Letter <u>0</u> : <u>1980</u> Feet From The <u>East</u> Line and <u>330</u> Feet From The <u>South</u> Line Section <u>2</u> Township <u>18-S</u> Range <u>34-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4013' DF	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCDC before plugging.
MIRU pulling unit. Install BOP.
TIH w/workstring and 2 7/8" bit. Clean out to 8600'. TOH w/bit and workstring.
TIH w/workstring to 8600' and load hole with salt gel mud (10 lb brine with 25 lbs of gel per barrel). TOH w/workstring.
By wireline, set CIBP at 8525'. Cap w/35' of class "H" cmt (1 sx).
Set CIBP at 5850'. Cap w/35' of class "H" cmt.
Set CIBP at 3300'. Cap w/35' of class "H" cmt.
Set CIBP at 2915'. Cap w/35' of class "H" cmt.
Set CIBP at 1680'. Cap w/35' of class "H" cmt.
Perforate squeeze hole at 370'. Establish circulation through squeeze hole.
Pump 94 sx of class "H" cmt down 2 7/8" csg and circulate to surface.
0. Cut off wellhead. Install dry hole marker. Clean location.

100' PLUG @ 4406

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard De Soto TITLE Eng. Tech. DATE 08-01-91

TYPE OR PRINT NAME Richard De Soto TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: