

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. NAME OF OPERATOR
FINA OIL & CHEMICAL COMPANY
3. ADDRESS OF OPERATOR
P. O. Box 2990, Midland, TX 79702-2990
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit Letter G, 1980' FNL & 1650' FEL

RECEIVED
Nov 15 4 14 PM '90
CAMP AREA

5. LEASE DESIGNATION AND SERIAL NO
LC 071857 B
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Continental A Com Fed
East A Fed
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
Lusk Strawn
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 6, T-19-S, R-32-E
12. COUNTY OR PARISH
Lea
13. STATE
N.M.

14. PERMIT NO.
API 30-025-20913
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
KB 3672.6, GL 3654.5

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Circulated hole with 10# salt gel from 6919' to surface.
- 2) Pumped 20 sx. C1 "H" plug from 6919'-6800'.
- 3) Pumped 100' plug between 5 1/2" & 8 5/8" casing @ 4089'-3989'.
- 4) Pumped 100' plug from 3300'-3200' outside and inside 5 1/2" casing.
- 5) Spot cement from 60' to surface, 10 sxs.
- 6) Remove wellhead and install marker, clean and rip location 6" deep.
- 7) Well P&A 1-17-90.

1611 11-12-90

18. I hereby certify that the foregoing is true and correct

SIGNED Neva Herndon
Neva Herndon

TITLE Senior Production Clerk

DATE 11-12-90

(This space for Federal or State office use)

APPROVED BY Orig. Signed by [Signature]

TITLE PETROLEUM ENGINEER

DATE 11-27-90

CONDITIONS OF APPROVAL, IF ANY:

Approved as to [Signature] of the well bore.
Liability under bond is required until
surface restoration is completed.

*See Instructions on Reverse Side