

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-9202	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Hanagan Petroleum Corp.		8. Farm or Lease Name Superior "A" State
3. Address of Operator Box 1737 Roswell, New Mexico		9. Well No. 1
4. Location of Well UNIT LETTER L , 1980 FEET FROM THE S LINE AND 660 FEET FROM THE W LINE, SECTION 2 TOWNSHIP 18-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Buckeye Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3925 KB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot a 30 sx plug in bottom to cover all perforation.
2. Load hole with mud laden fluid.
3. Shot & pulled 5600' - 5 1/2" casing.
4. Spot a 40 sx plug at stub of 5 1/2".
5. Spot a 40 sx plug at 3620'.
6. Shoot and pull 700' - 9 5/8" casing.
7. Spot a 40 sx plug at 700' and 360'.
8. Spot a 10 sx plug in top and erect a regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

HOBBS PIPE & SUPPLY

SIGNED *J. Miller* TITLE Agent DATE 4-30-67

APPROVED BY *John W. Runyan* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: