

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.D.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1258-1	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
Name of Operator		Vacuum Grayburg
TEXACO Inc.		San Andres Unit
Address of Operator		8. Farm or Lease Name
P. O. Box 728, Hobbs, New Mexico 88240		Vacuum Grayburg
Location of Well		San Andres Unit
UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>330</u> FEET FROM		9. Well No.
THE <u>North</u> LINE, SECTION <u>11</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.		1
15. Elevation (Show whether DF, RT, GR, etc.)		10. Field and Pool, or Wildcat
4007' (DF)		Vacuum Grayburg
		San Andres
		12. County
		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>				
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>				
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>				
OTHER <u>ADDL PERFS IN SAME ZONE</u> <input checked="" type="checkbox"/>							

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. PULL RODS & PUMP. INSTALL BOP. PULL TUBING.
2. CLEAN OUT STO 4740' (TD).
3. PERFORATE 4 1/2" CASING W/2-JSPF FROM 4688-4697 AND FROM 4713-4731'.
4. SET PKR ABOVE PERFORATIONS. ACIDIZE PERFORATIONS 4459-4731' W/6000 GALS 20% NEFE GELLED ACID IN 3-STAGES USING 200# ROCK SALT AND 200# MOTH BALLS BETWEEN STAGES. FLUSH W/25 BBLs WATER.
5. INSTALL PRODUCTION EQUIPMENT. TEST AND PLACE ON PRODUCTION.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 9-19-84

APPROVED BY [Signature] TITLE DATE SEP 21 1984

CONDITIONS OF APPROVAL, IF ANY: