Office	State of	New Mex	XICO		Form C-19	05			
District 1	Energy, Minerals	and Natur	al Resources		Revised March 25, 19	999			
1625 N. French Dr., Hobbs, NM 88240	<b>23</b> 7/			WELL API NO	D.				
District II OUL CONCEDIA TION DIVISION				30-025-22362					
1501 W. Gland Ave., Antesia, 140 60216				5. Indicate Type of Lease					
District III	1220 South	n St. Fran	cis Dr.	STATE					
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505					$\dashv$				
District 1				I .	& Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM				E-	-3072-3				
87505	CES AND REPORTS O	NIWELLO	<del></del>	7 Loose Nom	o on Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOS			IC DACV TO A	/. Lease Nam	e or Unit Agreement Nam	ie:			
DIFFERENT RESERVOIR. USE "APPLIC									
PROPOSALS.)	ATION FOR LEGMIT (FOR	JVI C-101) 1 O	K 30CH	East	E-K Queen Unit				
1. Type of Well:									
						İ			
Oil Well Gas Well Other				0 11 11 11					
2. Name of Operator				8. Well No.					
Kevin O. Butler & Associates					7				
3. Address of Operator				9. Pool name or Wildcat					
P. O. Box 1171 Midland, T	X 79702			E-K Queen; East					
4. Well Location					,				
G G	2310	North	•	1980	East				
1									
Unit Letter:	feet from the		line and	ieet		ne			
22		18S	34E		Lea				
Section	Township		nge	NMPM	County				
	10. Elevation (Show)	whether DI	R, RKB, RT, GR, et	c.)					
4008 GL									
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
		idicate 14		•					
					REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	<b>V</b>	REMEDIAL WOF	RK [	ALTERING CASING				
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND				
					ABANDONMENT				
PULL OR ALTER CASING   MULTIPLE   CASING TEST				.ND [	]				
	COMPLETION		CEMENT JOB						
			OTHER:						
OTHER:		ш	12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of						
	d operations. (Clearly st		inent details, and g	ive pertinent date	es including estimated dat	te of			
12. Describe proposed or complete		ate all perti							
12. Describe proposed or complete starting any proposed work). S		ate all perti							
12. Describe proposed or complete		ate all perti							
12. Describe proposed or complete starting any proposed work). S recompilation.	EE RULE 1103. For Mu	ate all perti	pletions: Attach w						
12. Describe proposed or complete starting any proposed work). S	EE RULE 1103. For Mu	ate all perti	pletions: Attach w						
12. Describe proposed or complete starting any proposed work). S recompilation.	EE RULE 1103. For Mu	ate all perti	pletions: Attach w						
<ul> <li>12. Describe proposed or complete starting any proposed work). S recompilation.</li> <li>1) MIRU. POOH w/ rods &amp;</li> </ul>	EE RULE 1103. For Mu	ate all perti	pletions: Attach w						
12. Describe proposed or complete starting any proposed work). S recompilation.	EE RULE 1103. For Mu	ate all perti	pletions: Attach w						
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> </ol>	EE RULE 1103. For Mu  c pump. Release TAC:  " casing at 4450 ft.	ate all perti altiple Com	pletions: Attach w	ellbore diagram	of proposed completion of				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/ 2 7/8" tubing wo</li> </ol>	EE RULE 1103. For Muck pump. Release TAC: " casing at 4450 ft. rk string and tag CIBP	ate all pertialtiple Compand POOH	pletions: Attach w  I w/ tubing.  Spot cement plu	ellbore diagram of the diagram of th	of proposed completion of				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> </ol>	EE RULE 1103. For Muck pump. Release TAC: " casing at 4450 ft.  rk string and tag CIBP	ate all pertialtiple Compand POOH	pletions: Attach w I w/ tubing. Spot cement plu 43 (BASE	g from 4450 to 4	of proposed completion of				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/ 2 7/8" tubing wo</li> </ol>	EE RULE 1103. For Muck pump. Release TAC: " casing at 4450 ft.  rk string and tag CIBP	ate all pertialtiple Compand POOH	pletions: Attach w I w/ tubing. Spot cement plu 43 (BASE	g from 4450 to 4	of proposed completion of				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> <li>SPOT IOD CEMEN</li> <li>Spot mud from 4350 ft. 6</li> </ol>	EE RULE 1103. For Muck pump. Release TAC: " casing at 4450 ft.  rk string and tag CIBP T PLO F 3143 o 2371 ft. Well mus	ate all pertialtiple Compand POOH	Spot cement plu	g from 4450 to 4	of proposed completion of				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> </ol>	EE RULE 1103. For Muck pump. Release TAC: " casing at 4450 ft.  rk string and tag CIBP	ate all pertialtiple Compand POOH	pletions: Attach w I w/ tubing. Spot cement plu 43 (BASE	g from 4450 to 4	of proposed completion of proposed completion of SEP 2010				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> <li>SPOT ISSI CEMEN &amp;</li> <li>Spot mud from 4350 ft.</li> <li>Continued on next page</li> </ol>	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOSE 143 0 2371 ft. Well mus	ate all pertialtiple Compand POOH	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of SALT  with Rule	350 ft. w/2030 lsd toment SEP 2000				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> <li>SPOT IOD CEMEN</li> <li>Spot mud from 4350 ft. 6</li> </ol>	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOSE 143 0 2371 ft. Well mus	ate all pertialtiple Compand POOH	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of SALT  with Rule	SEP 2000				
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> <li>SPOT ISSI CEMEN &amp;</li> <li>Spot mud from 4350 ft.</li> <li>Continued on next page</li> </ol>	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOSE 143 0 2371 ft. Well mus	ate all pertialtiple Compand POOH	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5AL7  with Rule  11/02  ge and belief.	SEP 2009  RECEIVED				
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 1/2  3) RIH w/2 7/8" tubing wo SPOT ISO CEMEN 4) Spot mud from 4350 ft. to Continued on next page	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOSE 143 0 2371 ft. Well mus	at 4450 ft.  at 4450 ft.  at be in	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5AL7  with Rule  11/02  ge and belief.	SEP 2019  RECLINED  Hobbs OCD	t.			
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>MIRU. POOH w/ rods &amp;</li> <li>RIH and set CIBP in 4 ½</li> <li>RIH w/2 7/8" tubing wo</li> <li>SPOT ISSI CEMEN &amp;</li> <li>Spot mud from 4350 ft.</li> <li>Continued on next page</li> </ol>	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOSE 143 0 2371 ft. Well mus	ate all pertialtiple Compand POOH	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5AL7  with Rule  11/02  ge and belief.	SEP 2000	t.			
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 1/2  3) RIH w/2 7/8" tubing wo SPOT IOO CEMEN 4) Spot mud from 4350 ft. of Continued on next page  I hereby certify that the information SIGNATURE	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOS F/3/43  0 2371 ft. Well mus  above is true and comple	at 4450 ft.  at 4450 ft.  at be in	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2000 RECEIVED ROBBS OCD DATE 9-09-20	t.			
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 ½  3) RIH w/2 7/8" tubing wo SPOT ISO CEMEN 4) Spot mud from 4350 ft. to Continued on next page  I hereby certify that the information SIGNATURE  Type or print name W. G. V.	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLOS F/3/43  0 2371 ft. Well mus  above is true and comple	at 4450 ft.  at 4450 ft.  at be in	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2019  RECLINED  Hobbs OCD	t.			
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 ½  3) RIH w/2 7/8" tubing wo SPOT ISSICEMENT & 25 POT IS	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLO F3143 0 2371 ft. Well mus  above is true and completely	at 4450 ft.  at 4450 ft.  at be in	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2000 RECEIVED ROBBS OCD DATE 9-09-20	t.			
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 ½  3) RIH w/2 7/8" tubing wo SPOT ISO CEMEN 4) Spot mud from 4350 ft. to Continued on next page  I hereby certify that the information SIGNATURE  Type or print name W. G. V.	EE RULE 1103. For Much pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  PLO F3143 0 2371 ft. Well mus  above is true and completely	at 4450 ft.  at 4450 ft.  at be in	Spot cement plu 43 (BASE compliance by	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2000 SEP	t. ∴			
12. Describe proposed or complete starting any proposed work). S recompilation.  1) MIRU. POOH w/ rods & 2) RIH and set CIBP in 4 ½  3) RIH w/2 7/8" tubing wo SPOT ISSUEMEN & 4) Spot mud from 4350 ft. Continued on next page  I hereby certify that the information SIGNATURE Type or print name W. G. V. (This space for State use)  ORIGINAL SIGNAPPROVED BY ARY W. WIN!	EE RULE 1103. For Muck pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  7 PLOS F 3143 0 2371 ft. Well mus  above is true and completely better the service of the service	at 4450 ft.  at 4450 ft.  at be in  TITLE	Spot cement plu 43 (BASE compliance by est of my knowled Operations Ma	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2000 RECEIVED ROBBS OCD DATE 9-09-20	t. ∴			
12. Describe proposed or complete starting any proposed work). Serecompilation.  1) MIRU. POOH w/ rods & Serecompilation.  1) MIRU. POOH w/ rods & Serecompilation.  2) RIH and set CIBP in 4 % Serecompilation work. Serecompilation with the information of the serecompilation with the information signature. Signature with the information signature. W. G.	EE RULE 1103. For Muck pump. Release TAC:  " casing at 4450 ft.  rk string and tag CIBP  7 PLOS F 3143 0 2371 ft. Well mus  above is true and completely better the service of the service	at 4450 ft.  at 4450 ft.  at be in  TITLE	Spot cement plu 43 (BASE compliance by est of my knowled Operations Ma	g from 4450 to 4  of 5ALT  with Rule  ///02  ge and belief.	SEP 2000 SEP	t. ∴			

a spegalaria e

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

## Form C-103

## 12) continued

- 5) Spot 25 sxs cement plug from 2371 to 2010 ft. (50 ft. above top of salt)
- 6) Spot mud from 2010 to 458 ft.
- 7) POOH w/ tubing work string. RIH and cut 4 ½" casing at 458 ft. (this is 50 ft. below the 8 5/8" casing shoe at 408 ft.). POOH w/ 4 ½" casing.
- 8) RIH w/ tubing work string and spot cement from 458 ft. to the surface. (116 sxs cement)
- 9) Cut off 8 5/8" casing 3 ft. below ground level.
- 10) Regulatory marker to be set in cement over wellbore.

## Det Walkore Disgram East E-K Queen Unit \*/

