STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	\Box	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

we, or corice acceives	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-7
FILE	1 SANTA FE, WEW MEXICO 0750;	Italiana Tura all sans
\ 	· · · · · · · · · · · · · · · · · · ·	Sa. Indicate Type of Lesse
U.S.G.S.	1	State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR	J .	
		
SUNDR	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
		7. Unit Agreement Name
1. OIL [V] 548 []		N HODDS (C/SA) HNTT
well X	OTHER.	N. HOBBS (G/SA) UNIT
2. Name of Operator		8. Farm of Lease Name
CUELL OTL COMPANY	•	SECTION 32
SHELL OIL COMPANY 3. Address of Operator		9. Well No.
		101
P. O. BOX 991, HOUSTON, TEXAS 77001		121
4. Location of Well	•	10. Field and Pool, or Wildcat
E	1730 FEET FROM THE NORTH LINE AND 330 FEET	HOBBS (G/SA)
UNIT LETTER	1730 PEET PROM THE LINE AND FEET P	
	10 C 20 E	
I THE WEST LINE, SECTI	10N 32 TOWNSHIP 18-S RANGE 38-E NA	wew. ///////////////////////////////////
mmmmm.	15. Elevation (Show whether DF, RT, GR, etc.)	12. County ()
	3647' DF	LEA ()
16. Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		ENT REPORT OF:
NOTICE OF I	NI ENTION 10.	•
		_
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING	OTHER	· ·
ODEN ADDITIONAL		
OPEN ADDITIONAL	PAY AND ACIDIZE . LXI	
		dia- estimated date of starting any propose
17. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, inclu	ding estimated date of starting day propose
work) SEE RULE 1103.		
7 07 4 4- 407011		
1. Clean out to 4270'	<u>†</u> .	
2. Perforate the follo	owing intervals: 4088' to 4090', 4128' to 4130	', 4147' to 4149', 4189'
+0 41021 42501 +0	4256' (20', 40 holes).	•
10 4192 , 4250 10	4230 (20 ; 40 110 103):	•
3. Acidize w/5670 gals	s 15% NEA.	
, ,		
1 Install mandustion	equipment and return well to production.	
4. Install production	equipment and return were to production.	
•	•	
	•	
·		
	•	
•		

18. I hereby certify that the information above is true and complete	e to the best of my knowledge and belief.	
with for A. J. FORE	SUPERVISOR REG. & PERMITTING	DATE OCTOBER 3, 1983
ORIGINAL SIGNED BY JERRY SEXTON	TITLE	OCT 121983
CONDITIONS OF APPROVAL, IF ANY		