

Subr. 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-23048
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A-29
8. Well No. #8
9. Pool name or Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3655' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Conoco, Inc.	
3. Address of Operator 10 Desta Dr., St. 100W, Midland, Tx 79705	
4. Well Location Unit Letter <u>K</u> : <u>2150</u> Feet From The <u>South</u> Line and <u>1800</u> Feet From The <u>West</u> Line Section <u>29</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3655' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TIH to 5,600'. Circulate hole with gelled mud.
2. Spot 30 sxs cement plug 3,560'-3,850'.
3. Cut and pull 5 1/2" csg. from 3,000'. Spot 25 sxs cement stub plug 2,950'-3,050'.
Add plug - 1500-1550' Salt Plug TO 5' TO 1600'
4. Perforate 8 5/8" csg. at 410'. Circulate 275 sxs cement thru perms to fill hole.
5. Install dryhole marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lee Roy Gaylor TITLE Mgr pool co DATE 4/14/99
TYPE OR PRINT NAME Lee Roy Gaylor TELEPHONE NO. 392 2577

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____