Form 9–331 Dec. 1973	Form Approved. color Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE 71-032233-A
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen on plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.	8. FARM OR LEASE NAME Bowers "A" Fed. Com. 31
1. Oli well     Image: Second se	9. WELL NO.
Exxon Corporation 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Hobbs-Drinkard
Box 1600; Midland, TX 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-18-S, R-38-E
below.) AT SURFACE: 1980' FNL, 660' FWL, Sec. 29, T18S, AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	12. COUNTY OR PARISH 13. STATE Lea New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 고등 3 : · · · · · · · · · · · · · · · · · ·
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3656 KDB
REQUEST FOR APPROVAL TO:       SUBSEQUENT REPORT OF:         TEST WATER SHUT-OFF	o 1 no 1 o 1 o 1 o 1 o 1 o 1 o 1 o 1 o 1
PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Place Hobbs Drinkard on Pump	*Hobbs Blinebry
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	lirectionally drilled, give subsurface locations and
See Attached Sheet.	4 of Pleanaphy (n another stranger) (n national stranger) (n nother stranger) of choase stranger) aged) attgob (sen notheds (n notheds (n notheds) (n notheds) (n notheds) (n n otheds)
	<ul> <li>Anthing of approval to berease with each of the second and the second and the second and and a second broad a block of the second</li></ul>
Subsurface Safety Valve: Manu. and Type	<u>⊐ ∛ ⊘</u> Set @ <u></u> Ft.
18. I hereby certify that the foregoing is true and correct SIGNED	
(This space for Federal or State of	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE DATE APR 3 1978

·· ' ,

\*See Instructions on Reverse Side

## WORKOVER PROCEDURE

- 1. Pull subsurface production equipment.
- 2. Run retrievable bridge plug and set at 6850'. Pump 20 bbls. of brine water into the Blinebry to establish pump in rate.
- 3. Cap bridge plug with five (5) sacks of sand.
- 4. Run cement retainer on workstring and set at 5760'.
- 5. Pressure up tubing-casing annulus to 1500 psi. Hold this pressure on the annulus while squeezing.
- 6. Squeeze cement the Blinebry perforations (5794' 5955') as follows:
  - a. Pump 20 bbls, fresh water pad.
  - b. Pump 200 sacks of Class "C" cement containing 5/10% Halad 9 (or equivalent).
  - c. Pump 100 sacks Class "C" cement containing five (5) 1bs. sand and two
     (2) 1bs. salt per sack. Hesitate if necessary to obtain squeeze.
  - NOTE: If a squeeze is not achieved, clear perforations, wait two (2) hours, and resqueeze as outlined in step six (6).
- 7. Pull out of retainer and reverse out excess cement. Pull tubing and packer.
- 8. Wait on cement.
- 9. Drill out cement retainer and cement to 5960'. Shut-in annulus and pressure test to 1500 psi for 30 minutes.
- 10. Circulate out sand and retrieve bridge plug.
- 11. Anchor tubing and place Drinkard on pump.