

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Fe
Rc 89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300-2523385
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-6002
7. Lease Name or Unit Agreement Name Central vacuum unit
8. Well No. 130
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Texaco E&P Inc.	
3. Address of Operator P.O. Box 3109 Midland, Texas 79701	
4. Well Location Unit Letter F : 1650 Feet From The North Line and 2236 Feet From The West Line Section 7 Township 18 S Range 35 E NMMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3980' D.F.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Notify N.M.O.C.D. of intent to Plug and Abandon well.
- 2.) T.I.H. with tub, tag cement at 4455'. Circulate wellbore with 9.5# plug mud.
- 3.) Spot 20sx cement plug at 3995' to 3895'. (Top of Queens 3945')
- 4.) Spot 35sx cement plug at 2976' to 2660'. (Top Yates - 2926' - B salt - 2730')
- 5.) Full, stretch and cut 4 1/2" c sq at 1562' & lay down same.
- 6.) Spot 85sx cement plug from 1612' - 1462'. (shoe plug) W.O.C. & TAG
- 7.) Spot 50sx cement plug from 100' - to surface.
- 8.) Rig down & cut off wellhead; cap well & install dry hole marker. Clean up location & move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R.J. Harding III TITLE Operating Engineer DATE 2/26/96
TYPE OR PRINT NAME R.J. Harding, III TELEPHONE NO. 915-688-481

(This space for State Use)

FEB 28 1996

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: