DISTRIBUTION SANTA FE	] [			0 1
SANTA FE	<del></del>			Supersedes Old C-102 and C-103
	NEW	MEXICO OIL CONSERVATIO	N COMMISSION	Effective 1-1-65
FILE				
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State Fee Fee
OPERATOR				5. State Oil & Gas Lease No. E-1582
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
OIL GAS WELL	OTHER-			7. Unit Agreement Name
2. Name of Operator LEATHERWOOD DRILLING CO.				8. Farm or Lease Name Atlantic-State
P.O. BOX 1352 ROSWELL, NEW MEXICO				9. Well No. 1
4. Location of Well  M  UNIT LETTER	330	West	330	10. Field and Pool, or Wildcat Field Wildcat
South		TOWNSHIP 18 S	35 F	NOM MARKET
	15. Elevation (Show whether DF, RT, GR, etc.) 3901.9 G.L.			12. County Lea
<sup>16.</sup>	Check Appropriate Bo	ox To Indicate Nature of	Notice, Report or	Other Data
NOTICE	E OF INTENTION TO:	:	SUBSEQU	ENT REPORT OF:
			<u> </u>	
PERFORM REMEDIAL WORK	PI	LUG AND ABANDON REMEDIAL	$\equiv$	ALTERING CASING
TEMPORARILY ABANDON	C		E DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	Cr	OTHER		_
OTHER				
17. Describe Proposed or Comp work) SEE RULE 1603.	oleted Operations (Clearly s	state all pertinent details, and gi	ve pertinent dates, inclu	ding estimated date of starting any proposed
work) SEE RULE 1703.	T.D. 4975 Dolo Mr.Joe Ramey a	mite. Well plugged a s follows:		
work) SEE RULE 1 103.	T.D. 4975 Dolo Mr.Joe Ramey a 25 sx. plug 49	mite. Well plugged a s follows: 75 - 4850	and abandoned o	
work) SEE RULE 1 103.	T.D. 4975 Dolor Mr.Joe Ramey a: 25 sx. plug 49	mite. Well plugged a s follows: 75 - 4850 50 - 2975 Base of S	and abandoned o	
work) SEE RULE 1 103.	T.D. 4975 Dolor Mr.Joe Ramey a: 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18	mite. Well plugged a s follows: 75 - 4850 50 - 2975 Base of S 00 - 1925 Top of Sa	and abandoned o Salt	
work) SEE RULE 1703.	T.D. 4975 Dolor Mr.Joe Ramey as 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18 25 sx. plug 3	mite. Well plugged a s follows: 75 - 4850 50 - 2975 Base of S 00 - 1925 Top of Sa 50 - 475 8-5/8" Sa	and abandoned o Salt	
work) SEE RULE 1 103.	T.D. 4975 Dolor Mr.Joe Ramey a: 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18	mite. Well plugged a s follows: 75 - 4850 50 - 2975 Base of S 00 - 1925 Top of Sa 50 - 475 8-5/8" Sa	and abandoned o Salt	
Work) SEE RULE 1703.  4-17-70  Drillin to dry	T.D. 4975 Dolor Mr.Joe Ramey at 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18 25 sx. plug 3 10 sx. plug at	mite. Well plugged a s follows: 75 - 4850 50 - 2975 Base of S 00 - 1925 Top of Sa 50 - 475 8-5/8" Sa	and abandoned of Salt alt urface casing	n verbal permission  d.Waiting on pits
Work) SEE RULE 1703.  4-17-70  Drillin to dry	T.D. 4975 Dolor Mr.Joe Ramey as 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18 25 sx. plug 3 10 sx. plug at ag mud spotted be before leveling	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Section 1925 Top of Section 1925 Section 1925 Section 1925 Section 1925 Section 1925 Base of Se	and abandoned of Salt alt urface casing	n verbal permission  d.Waiting on pits
Work) SEE RULE 1703.  4-17-70  Drillin to dry	T.D. 4975 Dolor Mr.Joe Ramey as 25 sx. plug 49 25 sx. plug 28 25 sx. plug 18 25 sx. plug 3 10 sx. plug at ag mud spotted be before leveling	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Section 1925 Top of Section 1925 Section 1925 Section 1925 Section 1925 Section 1925 Base of Se	and abandoned of Salt alt urface casing	n verbal permission  d.Waiting on pits
Drillin to dry ready f	T.D. 4975 Dolor Mr.Joe Ramey at 25 sx. plug 49 25 sx. plug 28 25 sx. plug 3 10 sx. plug at 10 sx. plug at 15 spection.	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Section 1925 Top of Section 1925 Section 1925 Section 1925 Section 1925 Section 1925 Base of Se	and abandoned of alt alt urface casing e marker erecteon.Will advise	n verbal permission  d.Waiting on pits
Drillin to dry ready f	T.D. 4975 Dolor Mr.Joe Ramey at 25 sx. plug 49 25 sx. plug 28 25 sx. plug 3 10 sx. plug at 10 sx. plug at 15 spection.	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Stop of S	and abandoned of alt alt urface casing e marker erecteon.Will advise	n verbal permission  d.Waiting on pits
Drillin to dry ready f	T.D. 4975 Dolor Mr.Joe Ramey at 25 sx. plug 49 25 sx. plug 28 25 sx. plug 3 10 sx. plug at 10 sx. plug at 15 spection.	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Store 1925 Top of Store 1925 Top of Store 1925 Surface  Etween plugs.Dry Hole and cleaning location	and abandoned of alt alt urface casing e marker erecteon.Will advise	n verbal permission  d.Waiting on pits when location is
Drillin to dry ready f	T.D. 4975 Dolor Mr.Joe Ramey at 25 sx. plug 49 25 sx. plug 28 25 sx. plug 3 10 sx. plug at 10 sx. plug at 15 spection.	mite. Well plugged as follows:  75 - 4850  50 - 2975 Base of Store 1925 Top of Store 1925 Top of Store 1925 Surface  Etween plugs.Dry Hole and cleaning location	and abandoned of Salt alt urface casing a marker erecte on. Will advise	n verbal permission  d.Waiting on pits when location is

## RECEIVED

APR 2 0 1970

OIL COMPUNITION COMM.