Office District I 1625 N. French Dr., Hobbs, NM 88240	State of New Me Energy, Minerals and Natu		Form C-10 Revised March 25, 199
District [OII COMPTENDE		WELL API NO. 30-025-24323
811 South First, Artesia, NM 88210 District III	OIL CONSERVATION		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran	· ·	·
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
	EC AND DEPONDE CO.		
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.) 1. Type of Well:	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLU TION FOR PERMIT" (FORM C-101) FO	G BACK TO A R SUCH	7. Lease Name or Unit Agreement Name Vacuum Grayburg
Oil Well 🖾 Gas Well	Other		
2. Name of Operator Texaco Exploration	& Production, Inc	•	8. Well No. 33
3. Address of Operator P. O. Box 3109, Mi	dland. TX 79072		9. Pool name or Wildcat
4. Well Location			Vacuum Grayburg - SA
Unit Letter E :	2630 feet from the North		The state of the s
22.2	10. Elevation (Show whether DR		
11. Check App	propriate Box to Indicate Na	ture of Notice. I	Report or Other Data
NOTICE OF IN I	ENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	ALTERING CASING
	CHANGE PLANS	COMMENCE DRIE	
			
		CASING TEST AN CEMENT JOB	ABANDONMENT L
OTHER:	COMPLETION	CEMENT JOB	ID
OTHER: 12. Describe proposed or complete of starting any proposed work). Sor recompilation.	d operations. (Clearly state all per EE RULE 1103. For Multiple Co	CEMENT JOB OTHER: extinent details, and mpletions: Attach	give pertinent dates, including estimated date wellbore diagram of proposed completion
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 2. Spot 50 Sx plug 4. Spot 50 Sx plug 4. Spot 25 Sx plug 5. Perf 6 holes @ 146. Perf 6 holes @ 4166.	d operations. (Clearly state all per EERULE 1103. For Multiple Correct RBP @ 4140, RIH yburg - San Andres) 1200'-3600' (Queen) 1LF, 9.5# Brine w/2 2800'-2600' (Yates, 100', Sqz 50 Sx plus 0', Sqz 50 Sx plus 0', Sqz 50 Sx plus	CEMENT JOB OTHER: extinent details, and mpletions: Attach W/4 1/2" WOC Tag S# gel P/1 B-Salt) Tag 1400'-12	I give pertinent dates, including estimated date wellbore diagram of proposed completion CICR set @ 4200', Sqz 75
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 2. Spot 50 Sx plug 2. Spot 50 Sx plug 2. Spot 25 Sx plug 2. Spot 25 Sx plug 2. Spot 26 Perf 6 holes @ 146. Perf 6 holes @ 417. Fill 4 1/2" Csg w	doperations. (Clearly state all persections). (Clearly state all persections). For Multiple Correct RBP @ 4140, RIH yburg - San Andres). (Queen). (Queen). (Queen). (Queen). (Queen). (Queen). (Queen). (Yates, 2800', Sqz 50 Sx plug.) (Yates, 27/30 Sx plug.) (Yates, 27/30 Sx plug.)	CEMENT JOB OTHER: extinent details, and mpletions: Attach W/4 1/2" WOC Tag Suff gel P/1 B-Salt) to 11 1410'-300 Gurf. Inst THE COHOURS PLUGGI	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. CMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED.
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 2). Spot 50 Sx plug 4. Spot 50 Sx plug 4. Spot 25 Sx plug 2. Perf 6 holes @ 146. Perf 6 holes @ 4166.	doperations. (Clearly state all persections). (Clearly state all persections). For Multiple Correct RBP @ 4140, RIH yburg - San Andres). (Queen). (Queen). (Queen). (Queen). (Queen). (Queen). (Queen). (Yates, 2800', Sqz 50 Sx plug.) (Yates, 27/30 Sx plug.) (Yates, 27/30 Sx plug.)	CEMENT JOB OTHER: extinent details, and mpletions: Attach W/4 1/2" WOC Tag Suff gel P/1 B-Salt) to 11 1410'-300 Gurf. Inst THE COHOURS PLUGGI	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. CMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED.
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/ws, Retrieved 4200'-4722' (Gray 2. Spot 50 Sx plug 2. Spot 50 Sx plug 2. Spot 25 Sx plug 2. Spot 25 Sx plug 2. Spot 26 Perf 6 holes @ 146. Perf 6 holes @ 417. Fill 4 1/2" Csg w	d operations. (Clearly state all persecond persons.) de RBP @ 4140, RIH gburg - San Andres) 1200'-3600' (Queen) 1LF, 9.5# Brine w/2 2800'-2600' (Yates, 100', Sqz 50 Sx plug) 10', Sqz 50 Sx plug	CEMENT JOB OTHER: extinent details, and mpletions: Attach W/4 1/2" WOC Tag Suff gel P/1 B-Salt) to 11 1410'-300 Gurf. Inst THE COHOURS PLUGGI	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. DMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED.
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 2. Spot 50 Sx plug 4. Spot 25 Sx plug 4. Spot 25 Sx plug 5. Perf 6 holes @ 14. 6. Perf 6 holes @ 41. Fill 4 1/2" Csg w. I hereby certify that the information about the start of th	d operations. (Clearly state all persecond persons.) de RBP @ 4140, RIH gburg - San Andres) 1200'-3600' (Queen) 1LF, 9.5# Brine w/2 2800'-2600' (Yates, 100', Sqz 50 Sx plug) 10', Sqz 50 Sx plug	CEMENT JOB OTHER: extinent details, and mpletions: Attach w/4 1/2" WOC Tag 25# gel P/1 B-Salt) to 1400'-13 410'-300 Gurf. Inst THE CO HOURS PLUGGI TO BE A	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. DMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED.
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 4	d operations. (Clearly state all persections). (Clearly state all persections). For Multiple Corrections of the RBP @ 4140, RIH (burg - San Andres). (Queen). (Queen)	CEMENT JOB OTHER: ratinent details, and mpletions: Attach w/4 1/2" WOC Tag S# gel P/I B-Salt) II 1410'-300 Gurf. Inst THE CC HOURS PLUGGI TO BE A	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. DMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED. Telephone No 688-4438
OTHER: 12. Describe proposed or complete of starting any proposed work). So or recompilation. 1. RIH w/WS, Retrieved 4200'-4722' (Gray 2. Spot 50 Sx plug 4. Spot 25 Sx plug 4. Spot 25 Sx plug 5. Perf 6 holes @ 14. Spot 25 Sx plug 6. Perf 6 holes @ 41. Fill 4 1/2" Csg was signatured. Type or print name // Ames	d operations. (Clearly state all persections). (Clearly state all persections). For Multiple Corrections of the RBP @ 4140, RIH (burg - San Andres). (Queen). (Queen)	CEMENT JOB OTHER: extinent details, and mpletions: Attach w/4 1/2" WOC Tag 25# gel P/1 B-Salt) to 1400'-13 410'-300 Gurf. Inst THE CO HOURS PLUGGI TO BE A	Igive pertinent dates, including estimated data wellbore diagram of proposed completion CICR set @ 4200', Sqz 75 BBL WOC Tag 200' (T-Salt) WOC Tag ' (8 5/8" shoe) WOC Tag tall dry hole marker. DMMISSION MUST BE NOTIFIED 24 PRIOR TO THE BEGINNING OF ING OPERATIONS FOR THE C-103 APPROVED. Telephone No 688-4438

5

dm