

November 11, 1985
Form No. 1-331

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Expires August 31, 1985

LEASE DESIGNATION AND SERIAL
LC 032233 (a)
IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
SHELL WESTERN E&P INC.
3. ADDRESS OF OPERATOR
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
UNIT LTR 0, 990' FSL, 1650' FEL

7. UNIT AGREEMENT NAME
N. HOBBS (G/SA) UNIT
8. FARM OR LEASE NAME
SECTION 30
9. WELL NO.
341
10. FIELD AND POOL, OR WILDCAT
HOBBS (G/SA)
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
SEC. 30, T18S, R38E
12. COUNTY OR PARISH
LEA
13. STATE
NM

14. PERMIT NO.
API #30-025-07443
15. ELEVATIONS (Show whether OF, AT, GR, etc.)
3655' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☒
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

1. Pull production equipment.
2. Set a CIBP @ 4205' & cap w/1 sack cmt.
3. Clean out to 4200'.
4. Set a RBP @ 4090' & pkr @ 4030'. Pres tst sqzd perf's 4056' - 4077' to 500#.
5. Run GR/CCL log from TD (4352') to 4000'. Perf San Andres 4103' - 4128' (2 JSPF, 16 holes).
6. Acidize perf's 4183' - 4196' w/1600 gals 15% HCl-NEA + 300# rock salt.
7. Acidize perf's 4103' - 4171' w/3600 gals 15% HCl-NEA.
8. Install production equipment and return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED E. J. FORE A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE NOVEMBER 11, 1985

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-26-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side