

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
L-3556

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT "C" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State FU
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.	10. Field and Pool, or Acreage Airstrip Upper Bone Sp
11. Elevation (Show whether DF, RT, GR, etc.) 3969' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	
OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate and test the additional Bone Springs as follows:

Pull rods, pump, tubing and anchor. Run in hole with retrievable bridge plug on wireline and set at 9000'. Test to 500 PSI. Perforate intervals 8317'-8346' with 2 DPJSPF. Run in hole with 3 joints of tailpipe, retrieving head on bottom, packer and tubing. Land tailpipe at ±8220'. Set packer. Run base gamma ray temp. survey. Acidize Bone Springs intervals 8317'-8346' with 3000 gal of 15% NE-HCL acid, tagged with radioactive material and additives. Flush acid to perms with 36 BBLs. of BW. Run after job gamma ray temp. survey. Swab. Release packer, drop down and retrieve retrievable bridge plug. Pull out of hole. Run in hole 2-3/8" tubing, anchor, pump and rods. Return well to production.

0+5-NMOCD,H 1-HOU 1-F. J. Nash 1-SUSP 1-PJS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Peter J. Sena TITLE Assist. Admin. Analyst DATE 4-4-83

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE MAR 6 1983

RECEIVED
APR 5 1983
HOBBS OFFICE