

Attachment to Form C-105

Hilliard Oil & Gas, Inc.
Union-State Com #1
Unit D, Sec 32, T-18-S, R-34-E
Lea County, New Mexico

Summary of DST's

DST #1 8164-8232' (68'), 30" IF, 90" ISI, 90" FF, 240" FSI. Rec 500' oil, 400' oil cut sulphur water, 500' sulphur water.

IHP - 3628# FFP - 409-595#
IFP - 100-360# FSIP - 3014#
ISIP - 3018# FHP - 3624#

DST #2 9315-9381 (66'), 25" IF, 90" ISI, 90" FF, 210" FSI. Recovered 10' oil, 1123 salt water.

IHP - 4102# FFP - 400-600#
IFP - 140-336# FSIP - 1835#
ISIP - 2252# FHP - 4097#

DST #3 9541-9602 (61') - Misrun

DST #4 9531-9602 (71'), 30" IF, 120" ISI, 60" FF, 240" FSI. Rec 15' drilling mud.

IHP - 4378# FFP - 68-68#
IFP - 59-59# FSIP - 585#
ISIP - 533# FHP - 4357#

DST #5 9020-9074' (54') straddle test, 30" IF, 60" ISI, 14" FF, lower packer seat failed. Rec. 250' water cut mud, 775' drilling mud.

IHP - 4226# FFP - 231-579#
IFP - 100-182# FSIP - Packer failed
ISIP - 3684# FHP - 4217#

DST #6 8950-9020' (70'), straddle test, 30" IF, 90" ISI, 90" FF, 270" FSI. Rec. 495' slightly oil cut mud.

IHP - 4203# FFP - 159-231#
IFP - 68-136# FSIP - 3684#
ISIP - 2896# FHP - 4203#

DST #7A 5205-5235 (30') straddle test. Misrun.

DST #7B 5205-5235 (30') straddle test, 15" IF, 30" ISI, 30" FF, 60" FSI. Rec. 150' drilling mud.

IHP - 2420# FFP - 63-100#
IFP - 40-44# FSIP - 1870#
ISIP - 1842# FHP - 2420#