

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OF COPIES REQUIRED
(Other Instruction
to be filled in)

Modified Form No.

1040-3160-4

3. LEASE DESIGNATION AND SERIAL NO.

NM 12413A

4. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sun McKay Federal

9. WELL NO.

#2

10. FIELD AND POOL, OR WILDCAT

Upper Bone Springs

11. SEC., T., R., M., OR BLK. AND
ACREAGE OR AREA

S10, T19S, R32E

12. COUNTY OR PARISH 13. STATE

LEA

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Petroleum Development Corporation

3a. Area Code & Phone No.

3. ADDRESS OF OPERATOR
9720 B Candelaria N.E. Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980
1980' FEL 1090 FNL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, OR, etc.)

3661 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Pressure test casing above perf. X

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Petroleum Development Corporation requests an extension to perform the following operations:
NOTIFY BLM ----

1) Pull tbg out of hole

2) Run Baker lok-set packer w/perforated nipple on top and bull plugged on bottom,
set above perforations f/8596' - 8610'.

3) Pressure test to 500 PSI f/15 min. USE PRESS. RECORDING CHART.

4) ATTACH THE PRESS. TEST CHART ----

RECEIVED

06 MAY 1990

DOE

CARL
AREAT

MAY 25 10 16 AM '90

RECEIVED
MAY 23 11 01 AM '90

RECEIVED

SIGNED Jim C. Johnson

TITLE Production Manager

DATE 5-14-90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

6-190

*See Instructions on Reverse Side

RECEIVED

JUN 04 1990

60
H2001