

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG4772

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Wessely Energy Corporation	State 11
3. Address of Operator	9. Well No.
2001 Bryan Tower, Suite 953, Dallas, Texas 75201	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER P 560 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 11 TOWNSHIP 18S RANGE 37E N.M.P.M.	Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3701 KB	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted 30sx plug from 7500 to 7600
2. Spotted 30sx plug from 6590 to 6690.
Above done with verbal approval on 6/1/78
3. Cut off 7" casing at approximately 6100'
4. Spot 100' plug at cut off point
5. Set ClBP at 4380' and dump 10sx plug on top ClBP
6. Spot 100' plug from 2800' to 2900' (base salt)
7. Spot 100' plug from 1660' to 1760' (top salt)
8. Spot 10sx surface plug
9. Cut off casing 3' below ground line. Surface cap to have location & operator welded on top.
10. Clean up location

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

Note: Dry hole marker will not be set as per request of City Hobbs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>Manager, Public Relations</u>	DATE <u>June 13, 1978</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u>Dist. L. Supv.</u>	DATE <u>JUN 13 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		