

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-7

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
L-4883	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "C" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name State "IA"
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Unit No. 1
4. Location of well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Annual Airstrip Wolfcamp
11. Elevation (Show whether DF, RT, GR, etc.) 3974.6 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate and test additional pay in the Wolfcamp as follows:

Pull rods, pump, tubing, and anchor. Set a retrievable bridge plug at apx. 10780. Perforate Wolfcamp intervals 10683'-90', 95'-97', 99'-10701', 04'-06', 11'-14', 18'-22', 29'-33', 40'-46', and 52'-58' with 2 DPJSPF. Run tubing, packer, and 3 joints tailpipe with retrieving head on bottom. Land retrieving head at apx. 10633' and set the packer. Run base gamma ray/temp. survey. Acidize the Wolfcamp with 5400 gal 15% NE HCL acid tagged with radioactive material and additives. Flush with formation water. Run after acid gamma ray/temp. survey. Swab. Pull the tubing, packer, and retrievable bridge plug. Run tubing anchor, pump, and rods. Return well to production.

0+4-NMOCD,H 1-HOU 1-SUSP 1-CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 2-4-83

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

FEB 8 1983

CONDITIONS OF APPROVAL, IF ANY: