

U. S. OIL & GAS COMMISSION  
P. O. BOX 1980  
HOBBS, NEW MEXICO 88240

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 21171

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Com "4" *Com*

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Bone Springs

11. SEC. T. R. M. OR RLK. AND  
SURVEY OR AREA

Sec 4-T19S-R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. OIL ☐ GAS ☒ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3660' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

POH with packer and tubing. Set CIBP at 8500', test casing 500#. Circulate hole with abandonment mud, spot 35' cement over CIBP. Cut casing at 5605', pull casing. Spot 7t sacks plug 5655'-5555'. Spot 35 sack plug 5457'-5357'. Spot 40 sack plug at 4125'. Spot 15 sack plug at 4156'. Spot 10 sack surface plug. Set dry hole marker. Clean and clear location. P&A 9-6-82.

RECEIVED  
SEP 16 1982

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*R. D. Pate*

TITLE

Area Engineer

DATE

9-15-82

(This space for Federal or State office use)

APPROVED BY

*Area Manager*

TITLE

DATE

6-27-86

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side