Form 9-331

COPY TO O. C. C.

(May 1963)	חרם		NILU S			"	ther instru	TRIPLICATE ctions on re		Budget Burea	iu No. 42		
	DEP		NT OF			TIOR re	rse side)		NIM O	DESIGNATION	AND SERI	AL NO.	
SUNDRY NOTICES AND REPORTS ON WELLS									!	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
(Do not	SUNDRY t use this form for Use "A							servoir.					
OIL WELL	GAS X 01	HER				· P P	FIVI		7. UNIT	AGREEMENT NA	ME		
2. NAME OF OP					— Įž	<u>} 但 ⊌</u>		<u> </u>	1 .	OR LEASE NAM			
Southland Royalty Company								<i>'</i> U	Feder	al "21" (Comm.		
3. ADDRESS OF		Wost	Midland	ነ ጥሮሌ	ac 7	,0701		SURVEY	9. WELL	NO.			
3. ADDRESS OF OPERATOR 1100 Wall Towers West, Midland, TExas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State of See also Space 17 below.) At surface 1 W									10. FIEL	10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.) At surface HOBBS, 182							Corb	Corbin South (Morrow)					
1980 '	FSL & 660/	FNE. S	ec. 21.	T-18	-S. R				11. SEC.,	T., R., M., OR B	LK. AND		
		, _			-, -				Sec.	21, T-18	-S, R-	-33 - E	
14. PERMIT NO.			5. ELEVATION	s (Show	whether	DF, RT, GR, e	etc.)		12. COUN	TY OR PARISH	13. ST/	ATE	
	•		3	830	Gr.				Le	a	N	M.	
16.	Che	ck Appro	opriate Bo	x To In	dicate	Nature o	f Notice	Report or	Other Dat	a			
check Appropriate box to malcule 14diole of 14diole, Report, of C										ENT REPORT OF:			
TEUT WATE	R SHUT-OFF	ם. יינו	C OR ALTER	CASING		,	VATER SHUT-	OFF.	_	REPAIRING W	velt.	\neg	
FRACTURE			TIPLE COMP	1			RACTURE TRE	-	<u> </u>	ALTERING CA	j-		
SHOOT OR	ACIDIZE	ABA	NDON*			s	HOOTING OR			ABANDONMEN			
REPAIR WE	LL	CHA	NGE PLANS	-		(mediate (X_	
(Other)			rova (Class		U ventine	au + du + all .	Complet	ion or Recomp	oletion Repo	rt and Log for	m.)	ting one	
proposed	OPOSED OR COMPLE work. If well is his work.) *	directional	y drilled, g	ive subsu	rface loc	cations and	measured a	nd true verti	cal depths f	or all markers	and zon	es perti-	
	g. Ran Com												
	& 32#, S-80												
	1/4# flocel												
	80. Open I L 15# salt,												
	AM 6-7-80.												
Install BO	P Nipple up	on BO	P after	24 h	r. P	ressur	e test 8	3 5/8" c	sg & BO	P to 1500	0# fo1		
	Okay. Com	pressi	ve str	of C	1 "C"	after	24 hr	is 2015 _]	psi @ 9	50°F. Di	rill		
ahead w/7	1/8" bit. 1/2" Casing	, to Eo	1100	-									
	Top:			32# \$	S - 80	ST&C							
			•		K-55	ST&C							
					S - 80	ST&C							
•					5-80	ST&C							
	Bottom: 9	52' 8	5/8"	32# \$	S - 80	ST&C							
,	me±=1. E1	101											
	Total: 51	.10'											
					•								
18. I hereby cer	rtify that the fore	going is tr	ue and corr	ect	-		<u> </u>						
SIGNED 🗡	Jonald	x c	wy	_ T IT	cle <u>Di</u>	strict	Operati	on Engi	neer da	те <u>7-9-</u> 8	30		
(This space	for Federal or St	ate office u	se)					1			1		
APPROVED) R Y			יויף	TLE			1		iùr Rlou te	RJ		
	NS OF APPROVA	L. IF ANY	:	_ 11,									

*See Instructions on Reverse Side

JUL 1 6 1980 U.S. GEORGEICAL SHINEY ROSVIEL, NEW ALKIED