

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator Kindred Petroleum Company	7. Unit Agreement Name
3. Address of Operator P. O. Box 411, Midland, Texas 79702	8. Farm or Lease Name State HS
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.	9. Well No. 1
	10. Field and Pool, or Wildcat West Vacuum Bone Spring

15. Elevation (Show whether DF, RT, GR, etc.)
4065' DF

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

On or about September 14, 1987, we propose to pull retrievable bridge plug at 8316' and set a cast iron bridge plug at 8360'.
Set cement retainer at 8010'; squeeze perforations at 8050-8054' with 50 sacks Class H cement - maximum pressure at 4000 psi;
Drill out cement retainer and cement; re-perforate at 8050-8054';
Swab test; run rods and pump and place well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. B. Buxby TITLE Agent DATE 9/9/87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 11 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 10 1987

OCD

HOBBS OFFICE