

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. LG-3862 |
| 7. Lease Name or Unit Agreement Name Creosote VM State |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Arkansas Junction SA West |

| |
|---|
| 4. Well Location Unit Letter <u>H</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>18S</u> Range <u>36E</u> NMPM <u>Lea</u> County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3847' GR |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter H : 1650 Feet From The North Line and 330 Feet From The East Line
Section 19 Township 18S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3847' GR

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

1. Set CIBP at 5250'. Cap with 35' of cement.
2. Freepoint casing, cut and pull. Cement Bond Log shows top of cement at 3885'. Expect to pull from 3700'±.
3. GIH w/tubing and load hole with salt gel mud.
4. Spot 35 sack plug 50' inside 5-1/2" stub. WOC. Tag plug at least 50' above 5-1/2" stub. If no tag, respot another plug.
5. Spot 35 sack plug across Bone Springs at 3152'.
6. Spot 50 sack plug from 2075' up to 1842' to cover top of Salt at 2018' and 8-5/8" shoe at 1822'. Tag this plug. Respot if necessary.
7. Set 15 sack plug at surface. Install regulation abandonment marker.

NOTE: NOTIFY NMOCD (393-6161) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE June 17, 1993

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 22 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 21 1993

OLD HORNS
SECTION