

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28182
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1113-1
7. Lease Name or Unit Agreement Name	Central Vacuum Unit
8. Well No.	162
9. Pool name or Wildcat	Vacuum Grayburg San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3984' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco Producing Inc.
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	4. Well Location Unit Letter <u>D</u> : <u>760</u> Feet From The <u>North</u> Line and <u>484</u> Feet From The <u>West</u> Line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3984' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) RUPU.
- 2) C/O to 4600'.
- 3) Perforate 5-1/2" csg 4247-4690'. 44 Intervals/55 Holes
- 4) Set 5-1/2" RBP @ 4700' & run 5-1/2" pkr.
- 5) Spt 70 gals 15% NEFE w/4 gals checkerson fr 4624-4690'. POH. Set pkr @ 4600'.
- 6) A/perfs 4624-4690' w/2500 gals 15% HCL NEFE 600# RS, 25 BS's, 12 Bbls X-linked brine, 25 gals ASP-530 @ 4 BPM. Swab.
- 7) Rel pkr & RBP. Reset RBP @ 4600'.
- 8) Spot 350 gals 15% NEFE w/20 Bbls Checkersol from 4247-4589'.
- 9) POH. Set pkr @ 4200'.
- 10) A/perfs 4247-4589' w/7050 gals 15% HCl, 3000# RS, 125 BS's, 60 Bbls X-Linked brine 71 gals ASP-530 @ 4 BPM.
- 11) Rel pkr & RBP. Set RBP @ 4700'. PSA 4200'.

(Over)

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE Richard DeSoto TITLE Engineering Technician DATE 12/07/90TYPE OR PRINT NAME R. B. DeSotoTELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

- 12) Scale squeeze.
- 13) TOH w/pkr & WS.
- 14) Run prod equip, test well and return to prod.