

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-28886</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <b>N. HOBBS (G/SA) UNIT</b>
2. Name of Operator <b>Shell Western E&amp;P Inc.</b>	8. Well No. <b>242</b>
3. Address of Operator <b>P.O. Box 576, Houston, TX 77001 (wck 5237)</b>	9. Pool name or Wildcat <b>HOBBS (G/SA)</b>
4. Well Location Unit Letter <b>N</b> : <b>200</b> Feet From The <b>SOUTH</b> Line and <b>1400</b> Feet From The <b>WEST</b> Line Section <b>30</b> Township <b>18S</b> Range <b>38E</b> NMPM <b>LEA</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3650.4' GR</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: **SET CIBP FOR WSO** ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Note: Verbal approval for the following, proposed operations was granted 12/15/94 by NMOCDC's Jerry Sexton.

1. POH w/prod eqmt.
2. TIH w/bit & scrpr. POH.
3. Set CIBP @ 4140'.
4. Inst prod eqmt & RTP. Should well begin to pmp off, a dump acid job of 1000 gal 15% HCl will be performed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *G. S. Nady* TITLE **MGR - ASSET ADMIN.** DATE **1/04/95**  
TYPE OR PRINT NAME **G. S. NADY** TELEPHONE NO. **713/544-3797**

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

**JAN 10 1995**