

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025028998

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG 7974

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Sherry M. State

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Lanexco, Inc.

8. Well No.

1

3. Address of Operator
P.O. Box 1206 Jal, NM 88252

9. Pool name or Wildcat
Airstrip Bone Spring

4. Well Location
Unit Letter D : 330 Feet From The N Line and 660 Feet From The W Line
Section 35 Township 18-S Range 34-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3991.6 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Alternate Plan

Rig up unit.

Pull rods and lay them down. Pull tubing.

Set 4½" CIBP at 9060' and dump 35 ft. cement on top.

Run a free point and shoot off casing at approximately 7940'.

Lay down 4½" casing. Circulate the hole with brine water and gel.

Set 100' plug inside 4½" stub and on top of 4½" 7990' - 7890'.

Set 100' plug 4890' - 4790'

Set 100' plug 4050' - 3950'

Set 100' plug 1790' - 1690'

Set 100' plug 450' - 350'

Cut off head. Set 10 ft. surface plug. Install dryhole marker.

Cover cellar. Cut off deadmen. Remove all equipment and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Copeland TITLE Production Supt. DATE 1-7-92

TYPE OR PRINT NAME Mike Copeland TELEPHONE NO. 395-3056

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY _____ TITLE _____ DATE JAN 10 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 09 1992

FROM
HONORARY OFFICE