

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30058

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

V-1358

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

Harvey E. Yates Company

3. Address of Operator

P.O. Box 1933, Roswell, New Mexico 88202

7. Lease Name or Unit Agreement Name

French 36 State

8. Well No.

1

9. Pool name or Wildcat

Undesignated Queen

4. Well Location

Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line

Section 36

Township 18S

Range 32E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☒

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CALL OCD I IN HOBBS, NM 24 HOURS PRIOR TO P & A. (1-505-393-6161)

1. PLUG # 1 = 422' CL "C" PLUG FROM 3950-4372' & !!TAG!!!
2. PLUG # 2 = 100' CMT ACROSS SHOE @ 3115' (3065-3165' PLUG)
3. CUT 5 1/2" @ +/- 2000' & PULL. (100' PLUG - 50' IN & OUT OF CUT OFF)
4. PLUG # 4 = 100' PLUG @ 1300' (TOP OF SALT)
5. PLUG # 5 = 100' PLUG ACROSS SURFACE SHOE FROM 350 TO 450'
6. PLUG # 6 = 10 SXS PLUG @ SURFACE w/ DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ray F. Nokes

TITLE Production Manager/Engineer DATE 12-15-89

TYPE OR PRINT NAME

Ray F. Nokes

skh

TELEPHONE NO 623-6601

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE _____ DATE DEC 22 1989


CONDITIONS OF APPROVAL, IF ANY:

DEC 20 1983

OCC
HOBBS OFFICE

WELL NAME: FRENCH 36 STATE # 1
 OPERATOR: HARVEY E. YATES COMPANY
 LEASE #: V-1359 API# 30-025-30059
 LOCATION: D. 660' FN & WL
 SEC. 36, T-18S, R-32E LRA CO., NM
 FIELD: UND. DELAWARE
 ELEVATION: 3729' GL (15' KB)

SPUD DATE: 10/2/87
 COMP DATE: 1/20/88
 TD: 10,250'
 PBTD: 7,089'
 DV TOOL @ 7,658'



CALL OCD I IN HOBBS, NM 24 HOURS PRIOR TO P & A. (1-505-393-6161)

1. PLUG # 1 = 422' CL "C" PLUG FROM 3950-4372' & !!!TAG!!!.
2. PLUG # 2 = 100' CMT ACROSS SHOE @ 3115' (3065-3165' PLUG)
3. CUT 5 1/2" @ +/- 2000' & PULL. (100' PLUG - 50' IN & OUT OF CUT OFF)
4. PLUG # 4 = 100' PLUG @ 1300' (TOP OF SALT)
5. PLUG # 5 = 100' PLUG ACROSS SURFACE SHOE FROM 350 TO 450'
6. PLUG # 6 = 10 SXS PLUG @ SURFACE w/ DRY HOLE MARKER.