

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30058
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V 1358
7. Lease Name or Unit Agreement Name French 36 State
8. Well No. 1
9. Pool name or Wildcat Querecho Plains Lower Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Harvey E. yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>FNL</u> Line and <u>660</u> Feet From The <u>FWL</u> Line Section <u>36</u> Township <u>18S</u> Range <u>32E</u> NMMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3729 GL (16' KB)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Plug #1 - 5 1/2" CIBP @ 6810' w/30' cmt on top (per Jerry Sexton OCD).
2. Plug #2 - 100' cmt across shoe @ 3115' (3065 - 3165' plug)
3. Cut 5 1/2" @ +/- 2000' and pull. (100' plug-50' in & out of cut off and tag plug.
4. Plug #3 - 100' plug @ 1300' (top of Salt).
5. Plug #4 - 100' plug across surface shoe from 350' to 450'.
6. Plug #5 - 10 SXS plug @ surface w/dry hole marker.
7. Clean location.

call OCD 24 hours prior to P & A

****APPROVED AS PER PAUL KAUTZ**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE Production Manager/Engineer DATE April 4, 1989
TYPE OR PRINT NAME Ray F. Nokes 505-623-6601 skh
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APR 6 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 5 1989

OCQ
MOBBS OFFICE