

Form 3160-5  
(July 1989)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED!  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.  
NM-0997

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
SOUTHLAND ROYALTY COMPANY

3. ADDRESS OF OPERATOR  
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.  
915-688-6906

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
660' FSL & 1980' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
QUERECHO

9. WELL NO.  
2

10. FIELD AND POOL, OR WILDCAT  
SOUTH CORBIN WOLFCAMP

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

28, T-18-S, R-33-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3780' GR

12. COUNTY OR PARISH  
LEA

13. STATE  
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) CLEAN UP PARAFFIN

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

HOT WATER WELL TO CLEAN UP DOWNHOLE PARAFFIN DEPOSITS.

OBTAIN OIL/WTR SAMPLES. DUMP 1 DRUM (55 GALS) TRETOLITE PAO-103F DOWN THE BACKSIDE. SOAK ALL DAY. START PUMPING UNIT. CURCLATE DURING NIGHT. THIS SHOULD CLEAN PARAFFIN OFF OF THE RODS AND INSIDE THE TBG. MIRU PULLING UNIT. TOOH W/11,241' ± 2-7/8" TBG. SET TEMP PROBE AT 11,222'. SET TAC ABOVE TOP PERFS. PUT WELL ON PROD. PUMP WELL THREE DAYS ±. MIRU HOT WATER COMPANY. RU ON BACKSIDE AND PUMP 200 BBLs OF HOT WATER W/9 GLS OF PAO-103F. RECORD THE EXACT TIME OF DAY THE JOB STARTS AND ENDS. PUMP RATE, TOTAL VOLUME PUMPED, HOT WATER TEMP IN AND OUT OF JOB. PUT UNIT BACK ON POC CONTROL W/ A SHORT SHUT IN TIME OF 5 MINUTES. PUMP WELL FOR TWO DAYS.

RESET THE POC DOWNTIME TO 30-45 ± MINS & PUMP THE WELL FOR THREE DAYS. MIRU HOT WATER COMPANY. PUMP 200 BBLs OF HOT WTR W/9 GLS OF PAO-103F. RECORD ALL INFORMATION. TOOH W/TBG & TEMP RECORDER ASSEMBLY. TIH W/TBG. TIH W/ROD STRING.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Wanda L. Perry*

TITLE

PRODUCTION ASST.

DATE

4-23-92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

5-6-92

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side