Submat 3 Copies to Appropriate Distinct Office	State of New M E: , Minerals and Natural R			Form C-1 Revised 1	
DISTRICT I P.O. Box 1980, Hobba, NM \$8240 DISTRICT II P.O. Drawer DD, Artesia, NM \$8210 OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088			WELL API NO. 30-025-30666 5. indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Ga	STATE	FEE
(DO NOT USE THIS FORM FOR PI DIFFERENT RESI	TICES AND REPORTS ON WE ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or	Uait Agreement Name	
OL X QAS WELL	OTHER		Philmex		
 Name of Operator Phillips Petroleum Address of Operator 			8. Well No. #39 9. Pool same or W	/ildent	
4001 Penbrook, Odes 4. Well Location Unit Letter:1	478 Feet From The South	Line and 1175		(Gb/SA) West	Line
Section 26	Township 17-S Ra	ange <u>1175</u> 33 N DF. RKB. RT. GR. etc.) 4140'RKB - 41	MPM	Lea	County
II. Check NOTICE OF IN	Appropriate Box to Indicate 1 TENTION TO:			Data EPORT OF:	
PERFORM REMEDIAL WORK		REMEDIAL WORK		ALTERING CASING	
PULL OR ALTER CASING			_	PLUG AND ABANDO	
prior to conversion to C	0 ₂ injection.	OTHER:			[
	0 ₂ injection.			PLUG AND ABANDO	

MI and RU DDU. NU BOP GIH with 2-7/8" 6.5# J-55 workstring OE to 4550' and spot 35 bbls 2% KCl w/LST water. Raise tbg to 3000 and swab dry, COOH with tubing and RD DDU.

MI and RU HLS Run GR-CCL and perforate Grayburg Sand 4 interval HLS mast truck. GR-CCL to CNL/LDT/Cal/GR. Install lubricator and pressure test to 2000 psi. GIH with 4" OD centralized hollow carrier gun loaded at 4 SPF. (10-13 grams per charge), spiral phasing. Perforate the following interval, 4335'-4341' 6 feet 24 shots. COOH with perforating gun. RD and MO Halliburton.

	re is jue and complete to the best of my know	(OVER)	
	$\sqrt{2}$	me Supervisor Reg/Proration	DATE 12-9-91
	Sanders		(915) THLEFHONE NO. 368-1488
(This space for State Use)			
APTROVED BY		TID.8	
CONDITIONS OF APPROVAL, IF ANY:			DATE

Install adjustable choke, block valve and pressure recorder on casing head outlet. Hook-up Port-a-Chek well tester on edge of location-insure flowline is well-staked. Route liquids (CO2 may be wet) to frac tank and lay at least 100' of line from gas outlet to vent stack. Precaution must be taken while venting well to atmosphere, SI well each night.

Decision to continue with current testing equipment and perforate/acidize additional zones pending flowback results.