

Form 3160-5
(July 1989)
(Formerly 9-331)

N. M. OIL CONS. COMMISSION
UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

HOBBS, NEW MEXICO 88240
OFFICE FOR NUMBER OF COPIES REQUIRED
CONTACT RECEIVING
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
~~023389-04~~ **LC-069420**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Southland Royalty Company

3. ADDRESS OF OPERATOR
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.
915-688-6800

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**Sec. 7, T18S, R33E
660' FNL & 330 FWL**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
West Corbin Federal

9. WELL NO.
19

10. FIELD AND POOL, OR WILDCAT
North Young (Bone Spring)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 7, T18S, R33E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-6-93 - MIRU. POH Sub pump. TIH w/DCS & bit.

5-7-93 - Drill CIBP @ 8530'. Push to 9200'. TOH. Perforate TIH.

5-8-93 - Stimulation - acdz w/4500 gals. Pentol-250. Swab. TOH.

5-9-93 - Land bottom of pump @ 8502'. Turn to production.

RECEIVED
MAY 13 10 31 AM '93
GOLDEN
MINE

David R. Glass
4 1993

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Assistant

DATE

5-11-93

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

***See Instructions on Reverse Side**

RECEIVED

JUN 21 1993

JUN 21 1993