June 1990)		O STATES OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
		ND MANAGEMENT	5. Lease Designation and Serial No.	
			NM 0997	
Do not use this fo U	orm for proposals to drill o	ID REPORTS ON WELLS or to deepen or reentry to a different reservoir. ERMIT—`` for such proposals	6. If Indian, Allottee or Tribe Name	
	7. If Unit or CA, Agreement Designation			
1. Type of Well Oil Gas Well Well	8. Well Name and No.			
2. Name of Operator	WEST CORBIN FED. # 28			
SOUTHLAND ROY	30-025-3/186			
3. Address and Telephone N	10. Field and Pool, or Exploratory Area			
P.O. BOX 5181 Location of Well (Footag	SOUTH CORBIN (WOLFCAMP			
A, 660 FNL & -T-18-S, R-33-	810 FEL		11. County or Parish, State LEA COUNTY	
CHECK	APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
	SUBMISSION	N		
	of Intent		Change of Plans	
געא			New Construction	
	ent Report	Plugging Back	Water Shut-Off	
	bandonment Notice	Altering Casing	Conversion to Injection	
	Jandonnen Norke	XX <sub>Other</sub> Scale Cleanout & rem	edia Dispose Water	
			(Note: Report results of multiple completion on Wei	
		sqz		
13. Describe Proposed or Col	mpleted Operations (Clearly state all per	rtinent details, and give pertinent dates, including estimated date of star	Completion or Recompletion Report and Log form	
give subsurface loca 1/28/92 - MIF	ations and measured and true vertical de	SQZ rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* DOX. RU SWAD. made two runs to clea	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally dril	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit scrapor	attons and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sv & stnds SDEN	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU pla	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally drill ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF	ations and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sw , & stnds. SDFN H w/bit ♥ scraper/11	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU pla 1300, POOJ, RU tstrs. GOH w/RBP &	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally drill ar tbg. R1s tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU	ations and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sw , & stnds. SDFN H w/bit <b>4</b> scraper/13 d pkr to 10638 load	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)• DOX. RU swab. made two runs to clea	Completion or Recompletion Report and Log form ing any proposed work. If well is directionally dril ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU RU swab. 2/1/92 - Plo	attons and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sw , & stnds. SDFN H w/bit <b>f</b> scraper/13 d pkr to 10638. load wireline. ran logs.	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. P00J. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ing any proposed work. If well is directionally drill ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU RU swab. 2/1/92 - Plo	attons and measured and true vertical de RU. POOH. GIH w/OS b , & stnds. RU swb & sw , & stnds. SDFN H w/bit ¶ scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear t	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. P00J. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ing any proposed work. If well is directionally drill ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH	attons and measured and true vertical de RU. POOH. GIH w/OS b , & stnds. RU swb & sw , & stnds. SDFN H w/bit ¶ scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear t	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. P00J. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ing any proposed work. If well is directionally drill ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH	attons and measured and true vertical de RU. POOH. GIH w/OS b , & stnds. RU swb & sw , & stnds. SDFN H w/bit ¶ scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear t	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. P00J. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ing any proposed work. If well is directionally dril ar tbg. R1s tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on RECENT	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moveo 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH	attons and measured and true vertical de RU. POOH. GIH w/OS b , & stnds. RU swb & sw , & stnds. SDFN H w/bit ¶ scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear t	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. P00J. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally drill ar tbg. Rls tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moved 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH tested pmp ac	attons and measured and true vertical de RU. POOH. GIH w/OS b , & stnds. RU swb & sw , & stnds. SDFN H w/bit ¶ scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear t	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. POOJ. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form. ting any proposed work. If well is directionally drill ar tbg. R1s tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on NELANS JAN 1 I 1993	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plo bit, scraper 1/30/92 - GIF Tested. Moved 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH tested pmp ac	attons and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sw , & stnds. SDFN H w/bit <b>f</b> scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear f ction. RDMO.	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. POOJ. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally drill ar tbg. R1s tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on RECENTED JAN 11 1993	
give subsurface loca 1/28/92 - MIF SDFN 1/29/92 - Plot bit, scraper 1/30/92 - GIF Tested. Moved 1/31/92 - RU RU swab. 2/1/92 - RIs 2/2/92 - TIH tested pmp ac	attons and measured and true vertical de RU. POOH. GIH w/OS b d Stnds. RU swb & sw , & stnds. SDFN H w/bit <b>f</b> scraper/12 d pkr to 10638. load wireline. ran logs pkr. Work RBP loose w/pmp, sub, shear f ction. RDMO.	rtinent details, and give pertinent dates, including estimated date of star epths for all markers and zones pertinent to this work.)* box. RU swab. made two runs to clear wabbed to top of fish/7500. PU plo 1300. POOJ. RU tstrs. GOH w/RBP & ded annulus w/170 bbls 2% KCL. SDF . acidize w/5000 gals 15% NEFe @ 6 e. TOH. TIH w/tbg. took, steel rods, fiberglass rods.	Completion or Recompletion Report and Log form ting any proposed work. If well is directionally drill ar tbg. R1s tac. NU BOP d rods. Tally out. GIH w/ pkr. Set RBP @ 10992 N .2 bpm. Tagged. RD wireli Spaced out & hung on NELLING JAN 1 I 1993	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5 (June 1990)	DEPARTMEN	UNITED STATES DEPARTMENT OF THE INTERIOR		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993		
	BUREAU OF	LAND MANAGEMENT	5.	Lease Designation and Serial No. NM 0997		
	SUNDRY NOTICES	6.	If Indian, Allottee or Tribe Name			
Do not use th	is form for proposals to dr Use "APPLICATION FO	eservoir.				
	SUBMI1	7. 1	If Unit or CA, Agreement Designation			
	Gas Well Dother	8. W	Vell Name and No.			
2. Name of Operator	Well Uther	WES	T CORBIN FEDERAL # 23			
SOUTHLAND	ROYALTY COMPANY	9. A	PI Well No.			
3. Address and Telepi	hone No.		5002531186			
P.O. BOX 5	1810 MIDLAND, TEXAS		Field and Pool, or Exploratory Area			
	Footage, Sec., T., R., M., or Survey D		UTH CORBIN (WOLFCAMP)			
	. & 810 FEL		County or Parish. State			
∽-T-18-S, R-				A COUNTY		
12. CHE	CK APPROPRIATE BOX	S) TO INDICATE NATURE OF NOTICE	E, HEPORT, C			
TYPE	OF SUBMISSION		FACTION	4 5		
	otice of Intent		<u>1993</u>	Change of Plans		
<b></b>		Recompletion	Ļ	New Construction		
LX Su	bsequent Report	Plugging Back	la Marijo, <b>∦</b>	Non-Routine Fracturing		
		Casing Repair	ل کم میں ا	Water Shut-Off		
L_J Fin	nal Abandonment Notice	Altering Casing	remove [	Conversion to Injection Dispose Water		
		calcium sulfat	e scale o	ote: Report results of multiple completion on Well		
13 Describe Proposed	or Completed Operations (Clearly state a	I pertinent details, and give pertinent dates, including estimated	(	empletion or Recompletion Report and Log form.)		
give subsurfac	e locations and measured and true verti	al depths for all markers and zones pertinent to this work.)*				
12/30/92 -						
		Rls tac. Install BOP. POOH w/tb (42 holes) SD	og. RU wire	line. Perf 10824-		
46'. (46 holes_ 10790-10810' (42 holes) SD 1/1/93 - RU wireline. PU stress frac tool. GIH to 10831-10843. POH w/out stress tool. PU						
overshot. RIH to 10382. pmpd 500 gals of aromatic & displaced w/2% KCL wtr. Caught stress to						
POH w/1500' of tbg. SDFN						
		tools. GIH w/overshot. POH w/t	bg & stres	s frac tool. LD fishing		
tools. SDF		ss frac tool. GIH to 10824-460	shoot POH			
1/4/95 - 8						
		10790-810 10790-810				
RD wirelin	e. PU mud . Perf	<pre>sub. GIH w/tbg. &amp; jts. landed</pre>		et tac. ND BOP. NU		
	. start in hole w/r					
1/5/92 - 0	Continue in hole w/p	np & rods. Load & test. good pu	mp action.	Turn back to		
productior	n. RDMO					
	<u>}</u>					
14. I hereby certify th	at the foregoing is true and correct	Production Assista	int	1/7/93		
Signed		Title		Date		
(This space for Fe	de a State office servit - f	- 11 -				
Approved by	JULICOTI TIC	Title		Date		
Conditions of appr	roval. if any and 2 1993					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.