



---

**marbob**  
energy corporation

---

July 17, 2001

Oil Conservation Division  
1625 North French Drive  
Hobbs, NM 88240

Attn: Chris Williams

Re: Lusk Deep Unit A #19  
Sec. 17-T19S-R32E  
660 FSL 1650 FWL

Mr. Williams:

When drilling the above referenced well, we exceeded 5° on our deviation surveys at 12000'. We do not have a directional survey at this depth. I talked to Paul Kautz of your office, and he said to calculate the maximum deviation going one way and send it to your attention. Our best estimate of direction is to the west since this is up-dip and normally that is the direction the bit will go.

If you have any questions, you can contact me at Marbob Energy - (505) 748-3303.  
Thank you for your help.

Sincerely,

Sheryl Baker

SB/djc

*Chris I talked with  
Marbot at the end  
of June and told them  
they would have to  
run directional survey  
they did not want to  
do it. They just would not  
take that answer  
and*